Recall Detail	
Ref No	**10001235**
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	GS F / RC F
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Replace fuel pump (TP8)
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The subject vehicles are equipped with a low-pressure fuel pump, located in the fuel tank, that supplies fuel to the fuel injection system through use of an impeller. The material in this impeller may swell sufficiently to interfere with surrounding components, potentially causing the fuel pump to become inoperative, when it is exposed to high fuel temperatures and high concentration of aromatic fuel components during operation. An inoperative fuel pump under these conditions may result in illumination of check engine and master warning indicators, engine no start, and/or vehicle stall.
Remedial Action	Replace fuel pump
Build Dates	GS F: January-2016 ~ May-2016 RC F: October-2014 ~ August-2015
Launch Date	1 May 2026
Tentative Date of Recall Completion	31 December 2027

1	JTHBP1BL20A000866
2	JTHBP1BL50A001882
3	JTHBP1BLX0A001909
4	JTHHP5BC005001735
5	JTHHP5BC005002058
6	JTHHP5BC205004409
7	JTHHP5BC305002510
8	JTHHP5BC405002791
9	JTHHP5BC605000315
10	JTHHP5BC605001805
11	JTHHP5BC605002078
12	JTHHP5BCX05000334