

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000308

製造商 Make: Mitsubishi Fuso Truck & Bus Corporation

型 號 Model: FV415, FV419, FV515, FV517, FV51J

項 目 Subject: HDT 中心軸承架裂紋的修改

HDT Center bearing rest crack modification

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

|    |               |               |
|----|---------------|---------------|
| 1  | <b>FV517P</b> | <b>A00128</b> |
| 2  | <b>FV517P</b> | <b>A00151</b> |
| 3  | <b>FV515S</b> | <b>A00134</b> |
| 4  | <b>FV515S</b> | <b>A00133</b> |
| 5  | <b>FV515S</b> | <b>A00132</b> |
| 6  | <b>FV515S</b> | <b>A00131</b> |
| 7  | <b>FV517P</b> | <b>A00130</b> |
| 8  | <b>FV515S</b> | <b>A00130</b> |
| 9  | <b>FV517P</b> | <b>A00135</b> |
| 10 | <b>FV515S</b> | <b>A00129</b> |
| 11 | <b>FV515S</b> | <b>A00136</b> |
| 12 | <b>FV515S</b> | <b>A00128</b> |
| 13 | <b>FV517P</b> | <b>A00127</b> |
| 14 | <b>FV515S</b> | <b>A00127</b> |
| 15 | <b>FV517P</b> | <b>A00126</b> |
| 16 | <b>FV515S</b> | <b>A00126</b> |
| 17 | <b>FV517P</b> | <b>A00125</b> |
| 18 | <b>FV515S</b> | <b>A00125</b> |
| 19 | <b>FV517P</b> | <b>A00124</b> |
| 20 | <b>FV517P</b> | <b>A00129</b> |
| 21 | <b>FV517P</b> | <b>A00142</b> |
| 22 | <b>FV515S</b> | <b>A00094</b> |
| 23 | <b>FV517P</b> | <b>A00148</b> |
| 24 | <b>FV517P</b> | <b>A00147</b> |
| 25 | <b>FV517P</b> | <b>A00146</b> |
| 26 | <b>FV517P</b> | <b>A00145</b> |
| 27 | <b>FV517P</b> | <b>A00144</b> |
| 28 | <b>FV515S</b> | <b>A00144</b> |
| 29 | <b>FV515S</b> | <b>A00135</b> |
| 30 | <b>FV515S</b> | <b>A00143</b> |
| 31 | <b>FV515S</b> | <b>A00123</b> |
| 32 | <b>FV515S</b> | <b>A00142</b> |
| 33 | <b>FV517P</b> | <b>A00141</b> |
| 34 | <b>FV515S</b> | <b>A00141</b> |

|    |               |               |
|----|---------------|---------------|
| 35 | <b>FV517P</b> | <b>A00140</b> |
| 36 | <b>FV515S</b> | <b>A00140</b> |
| 37 | <b>FV515S</b> | <b>A00139</b> |
| 38 | <b>FV515S</b> | <b>A00138</b> |
| 39 | <b>FV515S</b> | <b>A00137</b> |
| 40 | <b>FV517P</b> | <b>A00143</b> |
| 41 | <b>FV517P</b> | <b>A00098</b> |
| 42 | <b>FV517P</b> | <b>A00106</b> |
| 43 | <b>FV515S</b> | <b>A00106</b> |
| 44 | <b>FV515S</b> | <b>A00105</b> |
| 45 | <b>FV515S</b> | <b>A00104</b> |
| 46 | <b>FV515S</b> | <b>A00103</b> |
| 47 | <b>FV515S</b> | <b>A00102</b> |
| 48 | <b>FV515S</b> | <b>A00101</b> |
| 49 | <b>FV515S</b> | <b>A00124</b> |
| 50 | <b>FV515S</b> | <b>A00099</b> |
| 51 | <b>FV515S</b> | <b>A00108</b> |
| 52 | <b>FV515S</b> | <b>A00098</b> |
| 53 | <b>FV517P</b> | <b>A00097</b> |
| 54 | <b>FV515S</b> | <b>A00097</b> |
| 55 | <b>FV517P</b> | <b>A00096</b> |
| 56 | <b>FV515S</b> | <b>A00096</b> |
| 57 | <b>FV517P</b> | <b>A00095</b> |
| 58 | <b>FV515S</b> | <b>A00095</b> |
| 59 | <b>FV415P</b> | <b>A30142</b> |
| 60 | <b>FV515S</b> | <b>A00100</b> |
| 61 | <b>FV517P</b> | <b>A00113</b> |
| 62 | <b>FV517P</b> | <b>A00152</b> |
| 63 | <b>FV515S</b> | <b>A00122</b> |
| 64 | <b>FV515S</b> | <b>A00121</b> |
| 65 | <b>FV515S</b> | <b>A00120</b> |
| 66 | <b>FV515S</b> | <b>A00118</b> |
| 67 | <b>FV515S</b> | <b>A00117</b> |
| 68 | <b>FV515S</b> | <b>A00116</b> |

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000308

製造商 Make: Mitsubishi Fuso Truck & Bus Corporation

型 號 Model: FV415, FV419, FV515, FV517, FV51J

項 目 Subject: HDT 中心軸承架裂紋的修改

HDT Center bearing rest crack modification

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

|     |               |               |
|-----|---------------|---------------|
| 69  | <b>FV515S</b> | <b>A00115</b> |
| 70  | <b>FV515S</b> | <b>A00107</b> |
| 71  | <b>FV515S</b> | <b>A00114</b> |
| 72  | <b>FV517P</b> | <b>A00107</b> |
| 73  | <b>FV515S</b> | <b>A00113</b> |
| 74  | <b>FV515S</b> | <b>A00112</b> |
| 75  | <b>FV517P</b> | <b>A00111</b> |
| 76  | <b>FV515S</b> | <b>A00111</b> |
| 77  | <b>FV517P</b> | <b>A00110</b> |
| 78  | <b>FV515S</b> | <b>A00110</b> |
| 79  | <b>FV515S</b> | <b>A00109</b> |
| 80  | <b>FV517P</b> | <b>A00123</b> |
| 81  | <b>FV517P</b> | <b>A00114</b> |
| 82  | <b>FV415P</b> | <b>A30020</b> |
| 83  | <b>FV517P</b> | <b>A00149</b> |
| 84  | <b>FV415P</b> | <b>A30036</b> |
| 85  | <b>FV415P</b> | <b>A30035</b> |
| 86  | <b>FV415P</b> | <b>A30033</b> |
| 87  | <b>FV415P</b> | <b>A30025</b> |
| 88  | <b>FV415P</b> | <b>A30024</b> |
| 89  | <b>FV415P</b> | <b>A30023</b> |
| 90  | <b>FV415P</b> | <b>A30038</b> |
| 91  | <b>FV415P</b> | <b>A30021</b> |
| 92  | <b>FV415P</b> | <b>A30039</b> |
| 93  | <b>FV415P</b> | <b>A30019</b> |
| 94  | <b>FV415P</b> | <b>A30018</b> |
| 95  | <b>FV415P</b> | <b>A30017</b> |
| 96  | <b>FV415P</b> | <b>A30016</b> |
| 97  | <b>FV415P</b> | <b>A30015</b> |
| 98  | <b>FV415P</b> | <b>A30014</b> |
| 99  | <b>FV415P</b> | <b>A30013</b> |
| 100 | <b>FV415P</b> | <b>A30012</b> |
| 101 | <b>FV415P</b> | <b>A30022</b> |
| 102 | <b>FV415P</b> | <b>A30117</b> |
| 103 | <b>FV515S</b> | <b>A00001</b> |

|     |               |               |
|-----|---------------|---------------|
| 104 | <b>FV415P</b> | <b>A30140</b> |
| 105 | <b>FV415P</b> | <b>A30138</b> |
| 106 | <b>FV415P</b> | <b>A30137</b> |
| 107 | <b>FV415P</b> | <b>A30136</b> |
| 108 | <b>FV415P</b> | <b>A30135</b> |
| 109 | <b>FV415P</b> | <b>A30133</b> |
| 110 | <b>FV415P</b> | <b>A30037</b> |
| 111 | <b>FV415P</b> | <b>A30118</b> |
| 112 | <b>FV415P</b> | <b>A30005</b> |
| 113 | <b>FV415P</b> | <b>A30059</b> |
| 114 | <b>FV415P</b> | <b>A30055</b> |
| 115 | <b>FV415P</b> | <b>A30052</b> |
| 116 | <b>FV415P</b> | <b>A30050</b> |
| 117 | <b>FV415P</b> | <b>A30048</b> |
| 118 | <b>FV415P</b> | <b>A30043</b> |
| 119 | <b>FV415P</b> | <b>A30041</b> |
| 120 | <b>FV415P</b> | <b>A30040</b> |
| 121 | <b>FV415P</b> | <b>A30131</b> |
| 122 | <b>FV51JS</b> | <b>A00251</b> |
| 123 | <b>FV51JS</b> | <b>A00269</b> |
| 124 | <b>FV51JS</b> | <b>A00268</b> |
| 125 | <b>FV51JS</b> | <b>A00267</b> |
| 126 | <b>FV51JS</b> | <b>A00266</b> |
| 127 | <b>FV51JS</b> | <b>A00265</b> |
| 128 | <b>FV51JS</b> | <b>A00264</b> |
| 129 | <b>FV51JS</b> | <b>A00263</b> |
| 130 | <b>FV415P</b> | <b>A30011</b> |
| 131 | <b>FV51JS</b> | <b>A00255</b> |
| 132 | <b>FV51JS</b> | <b>A00272</b> |
| 133 | <b>FV51JP</b> | <b>A00221</b> |
| 134 | <b>FV51JP</b> | <b>A00218</b> |
| 135 | <b>FV517P</b> | <b>A00161</b> |
| 136 | <b>FV517P</b> | <b>A00157</b> |
| 137 | <b>FV517P</b> | <b>A00156</b> |
| 138 | <b>FV517P</b> | <b>A00155</b> |

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000308

製造商 Make: Mitsubishi Fuso Truck & Bus Corporation

型 號 Model: FV415, FV419, FV515, FV517, FV51J

項 目 Subject: HDT 中心軸承架裂紋的修改

HDT Center bearing rest crack modification

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

|     |               |               |
|-----|---------------|---------------|
| 139 | <b>FV517P</b> | <b>A00154</b> |
| 140 | <b>FV517P</b> | <b>A00153</b> |
| 141 | <b>FV51JS</b> | <b>A00260</b> |
| 142 | <b>FV51JS</b> | <b>A00282</b> |
| 143 | <b>FV515P</b> | <b>A00094</b> |
| 144 | <b>FV415P</b> | <b>A30003</b> |
| 145 | <b>FV415P</b> | <b>A30001</b> |
| 146 | <b>FV51JP</b> | <b>A00472</b> |
| 147 | <b>FV51JP</b> | <b>A00464</b> |
| 148 | <b>FV51JP</b> | <b>A00463</b> |
| 149 | <b>FV51JP</b> | <b>A00294</b> |
| 150 | <b>FV51JP</b> | <b>A00288</b> |
| 151 | <b>FV51JS</b> | <b>A00270</b> |
| 152 | <b>FV51JP</b> | <b>A00285</b> |
| 153 | <b>FV51JS</b> | <b>A00271</b> |
| 154 | <b>FV51JS</b> | <b>A00281</b> |
| 155 | <b>FV51JS</b> | <b>A00280</b> |
| 156 | <b>FV51JS</b> | <b>A00279</b> |
| 157 | <b>FV51JP</b> | <b>A00279</b> |
| 158 | <b>FV51JP</b> | <b>A00278</b> |
| 159 | <b>FV51JP</b> | <b>A00277</b> |
| 160 | <b>FV51JS</b> | <b>A00273</b> |
| 161 | <b>FV415P</b> | <b>A30006</b> |
| 162 | <b>FV51JP</b> | <b>A00286</b> |
| 163 | <b>FV515S</b> | <b>A00044</b> |
| 164 | <b>FV515S</b> | <b>A00059</b> |
| 165 | <b>FV515S</b> | <b>A00048</b> |
| 166 | <b>FV517S</b> | <b>A00047</b> |
| 167 | <b>FV515S</b> | <b>A00047</b> |
| 168 | <b>FV517S</b> | <b>A00046</b> |
| 169 | <b>FV515S</b> | <b>A00046</b> |
| 170 | <b>FV517S</b> | <b>A00045</b> |
| 171 | <b>FV515S</b> | <b>A00049</b> |
| 172 | <b>FV517S</b> | <b>A00044</b> |
| 173 | <b>FV517S</b> | <b>A00049</b> |

|     |               |               |
|-----|---------------|---------------|
| 174 | <b>FV517S</b> | <b>A00043</b> |
| 175 | <b>FV515S</b> | <b>A00043</b> |
| 176 | <b>FV517S</b> | <b>A00042</b> |
| 177 | <b>FV515S</b> | <b>A00042</b> |
| 178 | <b>FV517S</b> | <b>A00041</b> |
| 179 | <b>FV515S</b> | <b>A00041</b> |
| 180 | <b>FV517S</b> | <b>A00040</b> |
| 181 | <b>FV515S</b> | <b>A00040</b> |
| 182 | <b>FV515S</b> | <b>A00045</b> |
| 183 | <b>FV515S</b> | <b>A00054</b> |
| 184 | <b>FV517P</b> | <b>A00094</b> |
| 185 | <b>FV515S</b> | <b>A00058</b> |
| 186 | <b>FV517S</b> | <b>A00057</b> |
| 187 | <b>FV515S</b> | <b>A00057</b> |
| 188 | <b>FV517S</b> | <b>A00056</b> |
| 189 | <b>FV515S</b> | <b>A00056</b> |
| 190 | <b>FV517S</b> | <b>A00055</b> |
| 191 | <b>FV517S</b> | <b>A00048</b> |
| 192 | <b>FV517S</b> | <b>A00054</b> |
| 193 | <b>FV517S</b> | <b>A00038</b> |
| 194 | <b>FV517S</b> | <b>A00053</b> |
| 195 | <b>FV515S</b> | <b>A00053</b> |
| 196 | <b>FV517S</b> | <b>A00052</b> |
| 197 | <b>FV515S</b> | <b>A00052</b> |
| 198 | <b>FV517S</b> | <b>A00051</b> |
| 199 | <b>FV515S</b> | <b>A00051</b> |
| 200 | <b>FV517S</b> | <b>A00050</b> |
| 201 | <b>FV515S</b> | <b>A00050</b> |
| 202 | <b>FV515S</b> | <b>A00055</b> |
| 203 | <b>FV515S</b> | <b>A00018</b> |
| 204 | <b>FV517S</b> | <b>A00026</b> |
| 205 | <b>FV515S</b> | <b>A00026</b> |
| 206 | <b>FV515S</b> | <b>A00025</b> |
| 207 | <b>FV515S</b> | <b>A00024</b> |
| 208 | <b>FV515S</b> | <b>A00023</b> |

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000308

製造商 Make: Mitsubishi Fuso Truck & Bus Corporation

型 號 Model: FV415, FV419, FV515, FV517, FV51J

項 目 Subject: HDT 中心軸承架裂紋的修改

HDT Center bearing rest crack modification

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

|     |               |               |
|-----|---------------|---------------|
| 209 | <b>FV515S</b> | <b>A00022</b> |
| 210 | <b>FV515S</b> | <b>A00021</b> |
| 211 | <b>FV517S</b> | <b>A00039</b> |
| 212 | <b>FV515S</b> | <b>A00019</b> |
| 213 | <b>FV517S</b> | <b>A00028</b> |
| 214 | <b>FV515S</b> | <b>A00017</b> |
| 215 | <b>FV515S</b> | <b>A00016</b> |
| 216 | <b>FV515S</b> | <b>A00014</b> |
| 217 | <b>FV515S</b> | <b>A00011</b> |
| 218 | <b>FV515S</b> | <b>A00010</b> |
| 219 | <b>FV515S</b> | <b>A00009</b> |
| 220 | <b>FV515S</b> | <b>A00008</b> |
| 221 | <b>FV515S</b> | <b>A00003</b> |
| 222 | <b>FV515S</b> | <b>A00020</b> |
| 223 | <b>FV517S</b> | <b>A00033</b> |
| 224 | <b>FV517P</b> | <b>A00059</b> |
| 225 | <b>FV515S</b> | <b>A00038</b> |
| 226 | <b>FV517S</b> | <b>A00037</b> |
| 227 | <b>FV515S</b> | <b>A00037</b> |
| 228 | <b>FV517S</b> | <b>A00036</b> |
| 229 | <b>FV515S</b> | <b>A00036</b> |
| 230 | <b>FV517S</b> | <b>A00035</b> |
| 231 | <b>FV515S</b> | <b>A00035</b> |
| 232 | <b>FV515S</b> | <b>A00027</b> |
| 233 | <b>FV515S</b> | <b>A00034</b> |
| 234 | <b>FV515S</b> | <b>A00028</b> |
| 235 | <b>FV515S</b> | <b>A00033</b> |
| 236 | <b>FV517S</b> | <b>A00032</b> |
| 237 | <b>FV515S</b> | <b>A00032</b> |
| 238 | <b>FV515S</b> | <b>A00031</b> |
| 239 | <b>FV517S</b> | <b>A00030</b> |
| 240 | <b>FV515S</b> | <b>A00030</b> |
| 241 | <b>FV515S</b> | <b>A00029</b> |
| 242 | <b>FV515S</b> | <b>A00039</b> |
| 243 | <b>FV517S</b> | <b>A00034</b> |

|     |               |               |
|-----|---------------|---------------|
| 244 | <b>FV515S</b> | <b>A00079</b> |
| 245 | <b>FV517S</b> | <b>A00058</b> |
| 246 | <b>FV515S</b> | <b>A00083</b> |
| 247 | <b>FV517P</b> | <b>A00082</b> |
| 248 | <b>FV515S</b> | <b>A00082</b> |
| 249 | <b>FV517P</b> | <b>A00081</b> |
| 250 | <b>FV515S</b> | <b>A00081</b> |
| 251 | <b>FV517P</b> | <b>A00080</b> |
| 252 | <b>FV515S</b> | <b>A00084</b> |
| 253 | <b>FV517P</b> | <b>A00079</b> |
| 254 | <b>FV517P</b> | <b>A00084</b> |
| 255 | <b>FV515S</b> | <b>A00078</b> |
| 256 | <b>FV517S</b> | <b>A00077</b> |
| 257 | <b>FV515S</b> | <b>A00077</b> |
| 258 | <b>FV517S</b> | <b>A00076</b> |
| 259 | <b>FV515S</b> | <b>A00076</b> |
| 260 | <b>FV517S</b> | <b>A00075</b> |
| 261 | <b>FV515S</b> | <b>A00075</b> |
| 262 | <b>FV517S</b> | <b>A00074</b> |
| 263 | <b>FV515S</b> | <b>A00080</b> |
| 264 | <b>FV515S</b> | <b>A00089</b> |
| 265 | <b>FV517P</b> | <b>A00093</b> |
| 266 | <b>FV515S</b> | <b>A00093</b> |
| 267 | <b>FV517P</b> | <b>A00092</b> |
| 268 | <b>FV515S</b> | <b>A00092</b> |
| 269 | <b>FV517P</b> | <b>A00091</b> |
| 270 | <b>FV515S</b> | <b>A00091</b> |
| 271 | <b>FV517P</b> | <b>A00090</b> |
| 272 | <b>FV517P</b> | <b>A00083</b> |
| 273 | <b>FV517P</b> | <b>A00089</b> |
| 274 | <b>FV517S</b> | <b>A00073</b> |
| 275 | <b>FV517P</b> | <b>A00088</b> |
| 276 | <b>FV515S</b> | <b>A00088</b> |
| 277 | <b>FV517P</b> | <b>A00087</b> |
| 278 | <b>FV515S</b> | <b>A00087</b> |

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000308

製造商 Make: Mitsubishi Fuso Truck & Bus Corporation

型 號 Model: FV415, FV419, FV515, FV517, FV51J

項 目 Subject: HDT 中心軸承架裂紋的修改

HDT Center bearing rest crack modification

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

|     |               |               |
|-----|---------------|---------------|
| 279 | <b>FV517P</b> | <b>A00086</b> |
| 280 | <b>FV515S</b> | <b>A00086</b> |
| 281 | <b>FV517P</b> | <b>A00085</b> |
| 282 | <b>FV515S</b> | <b>A00085</b> |
| 283 | <b>FV515S</b> | <b>A00090</b> |
| 284 | <b>FV517S</b> | <b>A00062</b> |
| 285 | <b>FV515S</b> | <b>A00066</b> |
| 286 | <b>FV517S</b> | <b>A00065</b> |
| 287 | <b>FV517P</b> | <b>A00065</b> |
| 288 | <b>FV515S</b> | <b>A00065</b> |
| 289 | <b>FV517P</b> | <b>A00064</b> |
| 290 | <b>FV515S</b> | <b>A00064</b> |
| 291 | <b>FV517S</b> | <b>A00063</b> |
| 292 | <b>FV517P</b> | <b>A00074</b> |
| 293 | <b>FV515S</b> | <b>A00063</b> |
| 294 | <b>FV515S</b> | <b>A00067</b> |
| 295 | <b>FV517P</b> | <b>A00062</b> |
| 296 | <b>FV515S</b> | <b>A00062</b> |
| 297 | <b>FV517S</b> | <b>A00061</b> |
| 298 | <b>FV517P</b> | <b>A00061</b> |
| 299 | <b>FV515S</b> | <b>A00061</b> |
| 300 | <b>FV517P</b> | <b>A00060</b> |
| 301 | <b>FV515S</b> | <b>A00060</b> |
| 302 | <b>FV517S</b> | <b>A00059</b> |
| 303 | <b>FV517P</b> | <b>A00063</b> |
| 304 | <b>FV515S</b> | <b>A00070</b> |
| 305 | <b>FV415P</b> | <b>A30143</b> |
| 306 | <b>FV517P</b> | <b>A00073</b> |
| 307 | <b>FV515S</b> | <b>A00073</b> |
| 308 | <b>FV517P</b> | <b>A00072</b> |
| 309 | <b>FV515S</b> | <b>A00072</b> |
| 310 | <b>FV517S</b> | <b>A00071</b> |
| 311 | <b>FV517P</b> | <b>A00071</b> |
| 312 | <b>FV515S</b> | <b>A00071</b> |
| 313 | <b>FV517P</b> | <b>A00066</b> |

|     |               |               |
|-----|---------------|---------------|
| 314 | <b>FV517P</b> | <b>A00070</b> |
| 315 | <b>FV517S</b> | <b>A00066</b> |
| 316 | <b>FV517S</b> | <b>A00069</b> |
| 317 | <b>FV517P</b> | <b>A00069</b> |
| 318 | <b>FV515S</b> | <b>A00069</b> |
| 319 | <b>FV517S</b> | <b>A00068</b> |
| 320 | <b>FV517P</b> | <b>A00068</b> |
| 321 | <b>FV515S</b> | <b>A00068</b> |
| 322 | <b>FV517P</b> | <b>A00067</b> |
| 323 | <b>FV515S</b> | <b>A00074</b> |
| 324 | <b>FV517S</b> | <b>A00070</b> |
| 325 | <b>FV419P</b> | <b>A40107</b> |
| 326 | <b>FV415P</b> | <b>A40237</b> |
| 327 | <b>FV415P</b> | <b>A40160</b> |
| 328 | <b>FV415P</b> | <b>A40149</b> |
| 329 | <b>FV415P</b> | <b>A40132</b> |
| 330 | <b>FV419P</b> | <b>A40111</b> |
| 331 | <b>FV415P</b> | <b>A40111</b> |
| 332 | <b>FV419P</b> | <b>A40110</b> |
| 333 | <b>FV415P</b> | <b>A40162</b> |
| 334 | <b>FV419P</b> | <b>A40108</b> |
| 335 | <b>FV415P</b> | <b>A40163</b> |
| 336 | <b>FV419P</b> | <b>A40106</b> |
| 337 | <b>FV419P</b> | <b>A40105</b> |
| 338 | <b>FV419P</b> | <b>A40104</b> |
| 339 | <b>FV419P</b> | <b>A40103</b> |
| 340 | <b>FV419P</b> | <b>A40102</b> |
| 341 | <b>FV415P</b> | <b>A40102</b> |
| 342 | <b>FV419P</b> | <b>A40101</b> |
| 343 | <b>FV419P</b> | <b>A40100</b> |
| 344 | <b>FV419P</b> | <b>A40109</b> |
| 345 | <b>FV415P</b> | <b>A40217</b> |
| 346 | <b>FV419P</b> | <b>A40064</b> |
| 347 | <b>FV415P</b> | <b>A40235</b> |
| 348 | <b>FV415P</b> | <b>A40224</b> |

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000308

製造商 Make: Mitsubishi Fuso Truck & Bus Corporation

型 號 Model: FV415, FV419, FV515, FV517, FV51J

項 目 Subject: HDT 中心軸承架裂紋的修改

HDT Center bearing rest crack modification

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

|     |               |               |
|-----|---------------|---------------|
| 349 | <b>FV415P</b> | <b>A40223</b> |
| 350 | <b>FV415P</b> | <b>A40222</b> |
| 351 | <b>FV415P</b> | <b>A40221</b> |
| 352 | <b>FV415P</b> | <b>A40220</b> |
| 353 | <b>FV415P</b> | <b>A40161</b> |
| 354 | <b>FV415P</b> | <b>A40218</b> |
| 355 | <b>FV419P</b> | <b>A40098</b> |
| 356 | <b>FV415P</b> | <b>A40216</b> |
| 357 | <b>FV415P</b> | <b>A40215</b> |
| 358 | <b>FV415P</b> | <b>A40214</b> |
| 359 | <b>FV415P</b> | <b>A40213</b> |
| 360 | <b>FV415P</b> | <b>A40207</b> |
| 361 | <b>FV415P</b> | <b>A40206</b> |
| 362 | <b>FV415P</b> | <b>A40200</b> |
| 363 | <b>FV415P</b> | <b>A40168</b> |
| 364 | <b>FV415P</b> | <b>A40219</b> |
| 365 | <b>FV419P</b> | <b>A40072</b> |
| 366 | <b>FV415P</b> | <b>A40082</b> |
| 367 | <b>FV419P</b> | <b>A40081</b> |
| 368 | <b>FV419P</b> | <b>A40079</b> |
| 369 | <b>FV419P</b> | <b>A40078</b> |
| 370 | <b>FV419P</b> | <b>A40077</b> |
| 371 | <b>FV415P</b> | <b>A40077</b> |
| 372 | <b>FV419P</b> | <b>A40076</b> |
| 373 | <b>FV419P</b> | <b>A40099</b> |
| 374 | <b>FV419P</b> | <b>A40073</b> |
| 375 | <b>FV419P</b> | <b>A40083</b> |
| 376 | <b>FV419P</b> | <b>A40071</b> |
| 377 | <b>FV415P</b> | <b>A40071</b> |
| 378 | <b>FV419P</b> | <b>A40070</b> |
| 379 | <b>FV419P</b> | <b>A40069</b> |
| 380 | <b>FV419P</b> | <b>A40068</b> |
| 381 | <b>FV419P</b> | <b>A40067</b> |
| 382 | <b>FV419P</b> | <b>A40066</b> |
| 383 | <b>FV415P</b> | <b>A30141</b> |

|     |               |               |
|-----|---------------|---------------|
| 384 | <b>FV419P</b> | <b>A40074</b> |
| 385 | <b>FV419P</b> | <b>A40091</b> |
| 386 | <b>FV415P</b> | <b>A40238</b> |
| 387 | <b>FV419P</b> | <b>A40097</b> |
| 388 | <b>FV419P</b> | <b>A40096</b> |
| 389 | <b>FV415P</b> | <b>A40096</b> |
| 390 | <b>FV419P</b> | <b>A40095</b> |
| 391 | <b>FV415P</b> | <b>A40095</b> |
| 392 | <b>FV419P</b> | <b>A40094</b> |
| 393 | <b>FV418P</b> | <b>A40094</b> |
| 394 | <b>FV419P</b> | <b>A40082</b> |
| 395 | <b>FV419P</b> | <b>A40092</b> |
| 396 | <b>FV418P</b> | <b>A40083</b> |
| 397 | <b>FV419P</b> | <b>A40090</b> |
| 398 | <b>FV419P</b> | <b>A40089</b> |
| 399 | <b>FV419P</b> | <b>A40088</b> |
| 400 | <b>FV419P</b> | <b>A40087</b> |
| 401 | <b>FV419P</b> | <b>A40086</b> |
| 402 | <b>FV419P</b> | <b>A40085</b> |
| 403 | <b>FV419P</b> | <b>A40084</b> |
| 404 | <b>FV415P</b> | <b>A40099</b> |
| 405 | <b>FV419P</b> | <b>A40093</b> |
| 406 | <b>FV415P</b> | <b>A40489</b> |
| 407 | <b>FV415P</b> | <b>A40236</b> |
| 408 | <b>FV415P</b> | <b>A40498</b> |
| 409 | <b>FV415P</b> | <b>A40496</b> |
| 410 | <b>FV415P</b> | <b>A40495</b> |
| 411 | <b>FV415P</b> | <b>A40494</b> |
| 412 | <b>FV415P</b> | <b>A40493</b> |
| 413 | <b>FV415P</b> | <b>A40492</b> |
| 414 | <b>FV415P</b> | <b>A40502</b> |
| 415 | <b>FV415P</b> | <b>A40490</b> |
| 416 | <b>FV415P</b> | <b>A40504</b> |
| 417 | <b>FV415P</b> | <b>A40485</b> |
| 418 | <b>FV415P</b> | <b>A40484</b> |

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000308

製造商 Make: Mitsubishi Fuso Truck & Bus Corporation

型 號 Model: FV415, FV419, FV515, FV517, FV51J

項 目 Subject: HDT 中心軸承架裂紋的修改

HDT Center bearing rest crack modification

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

|     |               |               |
|-----|---------------|---------------|
| 419 | <b>FV415P</b> | <b>A40483</b> |
| 420 | <b>FV415P</b> | <b>A40482</b> |
| 421 | <b>FV415P</b> | <b>A40481</b> |
| 422 | <b>FV415P</b> | <b>A40480</b> |
| 423 | <b>FV415P</b> | <b>A40478</b> |
| 424 | <b>FV415P</b> | <b>A40477</b> |
| 425 | <b>FV415P</b> | <b>A40491</b> |
| 426 | <b>FV415P</b> | <b>A40533</b> |
| 427 | <b>FV415P</b> | <b>B30008</b> |
| 428 | <b>FV415P</b> | <b>B30007</b> |
| 429 | <b>FV415P</b> | <b>B30006</b> |
| 430 | <b>FV415P</b> | <b>B30004</b> |
| 431 | <b>FV415P</b> | <b>B30003</b> |
| 432 | <b>FV415P</b> | <b>B30002</b> |
| 433 | <b>FV415P</b> | <b>B30001</b> |
| 434 | <b>FV415P</b> | <b>A40499</b> |
| 435 | <b>FV415P</b> | <b>A40534</b> |
| 436 | <b>FV415P</b> | <b>A40464</b> |
| 437 | <b>FV415P</b> | <b>A40532</b> |
| 438 | <b>FV415P</b> | <b>A40531</b> |
| 439 | <b>FV415P</b> | <b>A40530</b> |
| 440 | <b>FV415P</b> | <b>A40529</b> |
| 441 | <b>FV415P</b> | <b>A40528</b> |
| 442 | <b>FV415P</b> | <b>A40525</b> |
| 443 | <b>FV415P</b> | <b>A40508</b> |
| 444 | <b>FV415P</b> | <b>A40505</b> |
| 445 | <b>FV415P</b> | <b>A40535</b> |
| 446 | <b>FV415P</b> | <b>A40416</b> |
| 447 | <b>FV415P</b> | <b>A40437</b> |
| 448 | <b>FV415P</b> | <b>A40436</b> |
| 449 | <b>FV415P</b> | <b>A40435</b> |
| 450 | <b>FV415P</b> | <b>A40434</b> |
| 451 | <b>FV415P</b> | <b>A40421</b> |
| 452 | <b>FV415P</b> | <b>A40420</b> |
| 453 | <b>FV415P</b> | <b>A40419</b> |

|     |               |               |
|-----|---------------|---------------|
| 454 | <b>FV415P</b> | <b>A40476</b> |
| 455 | <b>FV415P</b> | <b>A40417</b> |
| 456 | <b>FV415P</b> | <b>A40440</b> |
| 457 | <b>FV415P</b> | <b>A40379</b> |
| 458 | <b>FV415P</b> | <b>A40264</b> |
| 459 | <b>FV415P</b> | <b>A40263</b> |
| 460 | <b>FV415P</b> | <b>A40262</b> |
| 461 | <b>FV415P</b> | <b>A40261</b> |
| 462 | <b>FV415P</b> | <b>A40257</b> |
| 463 | <b>FV415P</b> | <b>A40254</b> |
| 464 | <b>FV415P</b> | <b>A40239</b> |
| 465 | <b>FV415P</b> | <b>A40418</b> |
| 466 | <b>FV415P</b> | <b>A40452</b> |
| 467 | <b>FV419P</b> | <b>A40063</b> |
| 468 | <b>FV415P</b> | <b>A40463</b> |
| 469 | <b>FV415P</b> | <b>A40462</b> |
| 470 | <b>FV415P</b> | <b>A40459</b> |
| 471 | <b>FV415P</b> | <b>A40458</b> |
| 472 | <b>FV415P</b> | <b>A40457</b> |
| 473 | <b>FV415P</b> | <b>A40456</b> |
| 474 | <b>FV415P</b> | <b>A40455</b> |
| 475 | <b>FV415P</b> | <b>A40438</b> |
| 476 | <b>FV415P</b> | <b>A40453</b> |
| 477 | <b>FV415P</b> | <b>A40439</b> |
| 478 | <b>FV415P</b> | <b>A40451</b> |
| 479 | <b>FV415P</b> | <b>A40446</b> |
| 480 | <b>FV415P</b> | <b>A40445</b> |
| 481 | <b>FV415P</b> | <b>A40444</b> |
| 482 | <b>FV415P</b> | <b>A40443</b> |
| 483 | <b>FV415P</b> | <b>A40442</b> |
| 484 | <b>FV415P</b> | <b>A40441</b> |
| 485 | <b>FV415P</b> | <b>A40465</b> |
| 486 | <b>FV415P</b> | <b>A40454</b> |
| 487 | <b>FV415P</b> | <b>A30267</b> |
| 488 | <b>FV415P</b> | <b>A30408</b> |

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000308

製造商 Make: Mitsubishi Fuso Truck & Bus Corporation

型 號 Model: FV415, FV419, FV515, FV517, FV51J

項 目 Subject: HDT 中心軸承架裂紋的修改

HDT Center bearing rest crack modification

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

|     |               |               |
|-----|---------------|---------------|
| 489 | <b>FV415P</b> | <b>A30276</b> |
| 490 | <b>FV415P</b> | <b>A30275</b> |
| 491 | <b>FV415P</b> | <b>A30274</b> |
| 492 | <b>FV415P</b> | <b>A30273</b> |
| 493 | <b>FV415P</b> | <b>A30271</b> |
| 494 | <b>FV415P</b> | <b>A30270</b> |
| 495 | <b>FV415P</b> | <b>A30279</b> |
| 496 | <b>FV415P</b> | <b>A30268</b> |
| 497 | <b>FV415P</b> | <b>A30284</b> |
| 498 | <b>FV415P</b> | <b>A30266</b> |
| 499 | <b>FV415P</b> | <b>A30260</b> |
| 500 | <b>FV415P</b> | <b>A30254</b> |
| 501 | <b>FV415P</b> | <b>A30249</b> |
| 502 | <b>FV415P</b> | <b>A30240</b> |
| 503 | <b>FV415P</b> | <b>A30238</b> |
| 504 | <b>FV415P</b> | <b>A30237</b> |
| 505 | <b>FV415P</b> | <b>A30236</b> |
| 506 | <b>FV415P</b> | <b>A30269</b> |
| 507 | <b>FV415P</b> | <b>A30328</b> |
| 508 | <b>FV419P</b> | <b>A40065</b> |
| 509 | <b>FV415P</b> | <b>A30398</b> |
| 510 | <b>FV415P</b> | <b>A30361</b> |
| 511 | <b>FV415P</b> | <b>A30355</b> |
| 512 | <b>FV415P</b> | <b>A30345</b> |
| 513 | <b>FV415P</b> | <b>A30339</b> |
| 514 | <b>FV415P</b> | <b>A30331</b> |
| 515 | <b>FV415P</b> | <b>A30277</b> |
| 516 | <b>FV415P</b> | <b>A30329</b> |
| 517 | <b>FV415P</b> | <b>A30232</b> |
| 518 | <b>FV415P</b> | <b>A30327</b> |
| 519 | <b>FV415P</b> | <b>A30326</b> |
| 520 | <b>FV415P</b> | <b>A30325</b> |
| 521 | <b>FV415P</b> | <b>A30319</b> |
| 522 | <b>FV415P</b> | <b>A30317</b> |
| 523 | <b>FV415P</b> | <b>A30312</b> |

|     |               |               |
|-----|---------------|---------------|
| 524 | <b>FV415P</b> | <b>A30291</b> |
| 525 | <b>FV415P</b> | <b>A30287</b> |
| 526 | <b>FV415P</b> | <b>A30330</b> |
| 527 | <b>FV415P</b> | <b>A30154</b> |
| 528 | <b>FV415P</b> | <b>A30164</b> |
| 529 | <b>FV415P</b> | <b>A30163</b> |
| 530 | <b>FV415P</b> | <b>A30162</b> |
| 531 | <b>FV415P</b> | <b>A30161</b> |
| 532 | <b>FV415P</b> | <b>A30159</b> |
| 533 | <b>FV415P</b> | <b>A30158</b> |
| 534 | <b>FV415P</b> | <b>A30157</b> |
| 535 | <b>FV415P</b> | <b>A30234</b> |
| 536 | <b>FV415P</b> | <b>A30155</b> |
| 537 | <b>FV415P</b> | <b>A30168</b> |
| 538 | <b>FV415P</b> | <b>A30152</b> |
| 539 | <b>FV415P</b> | <b>A30151</b> |
| 540 | <b>FV415P</b> | <b>A30149</b> |
| 541 | <b>FV415P</b> | <b>A30148</b> |
| 542 | <b>FV415P</b> | <b>A30147</b> |
| 543 | <b>FV415P</b> | <b>A30146</b> |
| 544 | <b>FV415P</b> | <b>A30145</b> |
| 545 | <b>FV415P</b> | <b>A30144</b> |
| 546 | <b>FV415P</b> | <b>A30156</b> |
| 547 | <b>FV415P</b> | <b>A30178</b> |
| 548 | <b>FV415P</b> | <b>A30417</b> |
| 549 | <b>FV415P</b> | <b>A30231</b> |
| 550 | <b>FV415P</b> | <b>A30230</b> |
| 551 | <b>FV415P</b> | <b>A30226</b> |
| 552 | <b>FV415P</b> | <b>A30224</b> |
| 553 | <b>FV415P</b> | <b>A30184</b> |
| 554 | <b>FV415P</b> | <b>A30183</b> |
| 555 | <b>FV415P</b> | <b>A30182</b> |
| 556 | <b>FV415P</b> | <b>A30165</b> |
| 557 | <b>FV415P</b> | <b>A30179</b> |
| 558 | <b>FV415P</b> | <b>A30167</b> |



# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000308

製造商 Make: Mitsubishi Fuso Truck & Bus Corporation

型 號 Model: FV415, FV419, FV515, FV517, FV51J

項 目 Subject: HDT 中心軸承架裂紋的修改

HDT Center bearing rest crack modification

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

|     |               |               |
|-----|---------------|---------------|
| 559 | <b>FV415P</b> | <b>A30177</b> |
| 560 | <b>FV415P</b> | <b>A30176</b> |
| 561 | <b>FV415P</b> | <b>A30174</b> |
| 562 | <b>FV415P</b> | <b>A30173</b> |
| 563 | <b>FV415P</b> | <b>A30172</b> |
| 564 | <b>FV415P</b> | <b>A30171</b> |
| 565 | <b>FV415P</b> | <b>A30169</b> |
| 566 | <b>FV415P</b> | <b>A30233</b> |
| 567 | <b>FV415P</b> | <b>A30181</b> |
| 568 | <b>FV415P</b> | <b>A30680</b> |
| 569 | <b>FV415P</b> | <b>A30405</b> |
| 570 | <b>FV415P</b> | <b>A30690</b> |
| 571 | <b>FV415P</b> | <b>A30689</b> |
| 572 | <b>FV415P</b> | <b>A30688</b> |
| 573 | <b>FV415P</b> | <b>A30687</b> |
| 574 | <b>FV415P</b> | <b>A30686</b> |
| 575 | <b>FV415P</b> | <b>A30683</b> |
| 576 | <b>FV415P</b> | <b>A30692</b> |
| 577 | <b>FV415P</b> | <b>A30681</b> |
| 578 | <b>FV415P</b> | <b>A30693</b> |
| 579 | <b>FV415P</b> | <b>A30679</b> |
| 580 | <b>FV415P</b> | <b>A30678</b> |
| 581 | <b>FV415P</b> | <b>A30675</b> |
| 582 | <b>FV415P</b> | <b>A30674</b> |
| 583 | <b>FV415P</b> | <b>A30673</b> |
| 584 | <b>FV415P</b> | <b>A30672</b> |
| 585 | <b>FV415P</b> | <b>A30671</b> |
| 586 | <b>FV415P</b> | <b>A30670</b> |
| 587 | <b>FV415P</b> | <b>A30682</b> |
| 588 | <b>FV419P</b> | <b>A40052</b> |
| 589 | <b>FV419P</b> | <b>A40062</b> |
| 590 | <b>FV419P</b> | <b>A40061</b> |
| 591 | <b>FV419P</b> | <b>A40060</b> |
| 592 | <b>FV415P</b> | <b>A40060</b> |
| 593 | <b>FV415P</b> | <b>A40057</b> |

|     |               |               |
|-----|---------------|---------------|
| 594 | <b>FV419P</b> | <b>A40055</b> |
| 595 | <b>FV415P</b> | <b>A40055</b> |
| 596 | <b>FV415P</b> | <b>A30691</b> |
| 597 | <b>FV415P</b> | <b>A40053</b> |
| 598 | <b>FV415P</b> | <b>A30667</b> |
| 599 | <b>FV419P</b> | <b>A40051</b> |
| 600 | <b>FV419P</b> | <b>A40050</b> |
| 601 | <b>FV415P</b> | <b>A40050</b> |
| 602 | <b>FV419P</b> | <b>A40049</b> |
| 603 | <b>FV418P</b> | <b>A40047</b> |
| 604 | <b>FV415P</b> | <b>A40047</b> |
| 605 | <b>FV415P</b> | <b>A40046</b> |
| 606 | <b>FV418P</b> | <b>A40040</b> |
| 607 | <b>FV415P</b> | <b>A40054</b> |
| 608 | <b>FV415P</b> | <b>A30522</b> |
| 609 | <b>FV415P</b> | <b>A30585</b> |
| 610 | <b>FV415P</b> | <b>A30583</b> |
| 611 | <b>FV415P</b> | <b>A30556</b> |
| 612 | <b>FV415P</b> | <b>A30554</b> |
| 613 | <b>FV415P</b> | <b>A30540</b> |
| 614 | <b>FV415P</b> | <b>A30533</b> |
| 615 | <b>FV415P</b> | <b>A30532</b> |
| 616 | <b>FV415P</b> | <b>A30669</b> |
| 617 | <b>FV415P</b> | <b>A30529</b> |
| 618 | <b>FV415P</b> | <b>A30594</b> |
| 619 | <b>FV415P</b> | <b>A30521</b> |
| 620 | <b>FV415P</b> | <b>A30519</b> |
| 621 | <b>FV415P</b> | <b>A30511</b> |
| 622 | <b>FV415P</b> | <b>A30509</b> |
| 623 | <b>FV415P</b> | <b>A30507</b> |
| 624 | <b>FV415P</b> | <b>A30506</b> |
| 625 | <b>FV415P</b> | <b>A30460</b> |
| 626 | <b>FV415P</b> | <b>A30454</b> |
| 627 | <b>FV415P</b> | <b>A30530</b> |
| 628 | <b>FV415P</b> | <b>A30612</b> |

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000308

製造商 Make: Mitsubishi Fuso Truck & Bus Corporation

型 號 Model: FV415, FV419, FV515, FV517, FV51J

項 目 Subject: HDT 中心軸承架裂紋的修改

HDT Center bearing rest crack modification

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

|     |               |               |
|-----|---------------|---------------|
| 629 | <b>FV415P</b> | <b>B30009</b> |
| 630 | <b>FV415P</b> | <b>A30666</b> |
| 631 | <b>FV415P</b> | <b>A30665</b> |
| 632 | <b>FV415P</b> | <b>A30664</b> |
| 633 | <b>FV415P</b> | <b>A30663</b> |
| 634 | <b>FV415P</b> | <b>A30662</b> |
| 635 | <b>FV415P</b> | <b>A30657</b> |
| 636 | <b>FV415P</b> | <b>A30654</b> |
| 637 | <b>FV415P</b> | <b>A30588</b> |
| 638 | <b>FV415P</b> | <b>A30651</b> |

|     |               |               |
|-----|---------------|---------------|
| 639 | <b>FV415P</b> | <b>A30591</b> |
| 640 | <b>FV415P</b> | <b>A30610</b> |
| 641 | <b>FV415P</b> | <b>A30609</b> |
| 642 | <b>FV415P</b> | <b>A30608</b> |
| 643 | <b>FV415P</b> | <b>A30604</b> |
| 644 | <b>FV415P</b> | <b>A30603</b> |
| 645 | <b>FV415P</b> | <b>A30600</b> |
| 646 | <b>FV415P</b> | <b>A30597</b> |
| 647 | <b>FV415P</b> | <b>A30668</b> |
| 648 | <b>FV415P</b> | <b>A30653</b> |