

## Recall Detail

<b>Ref No</b>	<b>10000371</b>
<b>Manufacturer</b>	Subaru
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	Impreza S204
<b>Dealer (phone no)</b>	Motor Image (HK) Ltd (23936118)
<b>Subject</b>	Inspect air intake duct and fuel supply line
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	It is possible that the air intake duct contact with the fuel supply line. This could cause damage on the fuel supply line, in isolated cases can lead to leakage.
<b>Remedial Action</b>	As a precaution, replace the affected vehicle air intake duct and check the fuel supply line between air intake duct contact area in the engine compartment. If necessary, also replace the fuel supply line.
<b>Build Dates</b>	June 2006
<b>Launch Date</b>	28 Nov 2011
<b>Tentative Date of Recall Completion</b>	31 Dec 2019

1	<b>GDB-021409</b>
2	<b>GDB-024407</b>
3	<b>GDB-032185</b>
4	<b>GDB-032732</b>
5	<b>GDB-038785</b>
6	<b>GDB-038792</b>
7	<b>GDB-038794</b>
8	<b>GDB-038801</b>
9	<b>GDB-038802</b>
10	<b>GDB-038804</b>
11	<b>GDB-038811</b>
12	<b>GDB-038812</b>
13	<b>GDB-038813</b>
14	<b>GDB-038814</b>
15	<b>GDB-038816</b>
16	<b>GDB-038817</b>
17	<b>GDB-038820</b>