

Recall Detail	
<b>Ref No</b>	<b>10000385</b>
<b>Manufacturer</b>	BMW
<b>Vehicle Class</b>	Passenger Car
<b>Model/Type</b>	X5, X6, 5 series, 6 series and 7 series (E7x, F0x and F1x)
<b>Dealer (phone no)</b>	31882677
<b>Subject</b>	Replace the exhaust turbocharger's additional coolant pump
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below: (Last Seven Numbers)
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	A crack may develop in the plastic housing of the additional coolant pump. Moisture can get through the crack and into the electronics. A short-circuit to earth then leads to melting of the plug connections and the housing.
<b>Remedial Action</b>	Replace the additional coolant pump
<b>Build Dates</b>	03/2011 – 08/2011
<b>Launch Date</b>	16/04/2012
<b>Tentative Date of Recall Completion</b>	31/10/2012

1	<b>C272430</b>
2	<b>CY56151</b>
3	<b>CY56159</b>