

Recall Detail	
<b>Ref No</b>	<b>10000386</b>
<b>Manufacturer</b>	MINI
<b>Vehicle Class</b>	Passenger Car
<b>Model/Type</b>	R5x, R60
<b>Dealer (phone no)</b>	31882677
<b>Subject</b>	Replace the exhaust turbocharger's additional coolant pump
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below: (Last Seven Numbers)
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	A crack may develop in the plastic housing of the additional coolant pump. Moisture can get through the crack and into the electronics. A short-circuit to earth then leads to melting of the plug connections and the housing.
<b>Remedial Action</b>	Replace the additional coolant pump
<b>Build Dates</b>	03/2011 – 04/2011
<b>Launch Date</b>	16/04/2012
<b>Tentative Date of Recall Completion</b>	31/10/2012

1	<b>T149698</b>
2	<b>TY78766</b>
3	<b>TY78767</b>
4	<b>TY78773</b>
5	<b>TY78778</b>
6	<b>TY78779</b>
7	<b>TZ04297</b>
8	<b>TZ04345</b>
9	<b>WM20590</b>
10	<b>WM20592</b>
11	<b>WM20597</b>
12	<b>WM20602</b>
13	<b>WM20604</b>
14	<b>WM20611</b>
15	<b>WM20616</b>
16	<b>WM20627</b>
17	<b>WM20628</b>
18	<b>WM20629</b>
19	<b>WM20631</b>
20	<b>WM23089</b>