

Recall Detail	
<b>Ref No</b>	<b>10000387</b>
<b>Manufacturer</b>	Rolls-Royce
<b>Vehicle Class</b>	Passenger Car
<b>Model/Type</b>	Ghost
<b>Dealer (phone no)</b>	31936999
<b>Subject</b>	Auxiliary water pump replacement
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below: (Last Seven Numbers)
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	A crack may develop in the plastic housing of the additional coolant pump. Moisture can get through the crack and into the electronics. A short-circuit to earth then leads to melting of the plug connections and the housing.
<b>Remedial Action</b>	Replace the auxiliary water pump
<b>Build Dates</b>	07-04-2011 – 02-06-2011
<b>Launch Date</b>	12/04/2012
<b>Tentative Date of Recall Completion</b>	31/10/2012

1	<b>UH15363</b>
2	<b>UH15375</b>
3	<b>UH15382</b>
4	<b>UH15391</b>
5	<b>UH15397</b>
6	<b>UH15408</b>
7	<b>UH15409</b>