

Recall Detail	
<b>Ref No</b>	<b>10000388</b>
<b>Manufacturer</b>	BMW
<b>Vehicle Class</b>	Motor Cycle
<b>Model/Type</b>	S 1000 RR
<b>Dealer (phone no)</b>	31882677
<b>Subject</b>	Installing new conrod bolts
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below: (Last Seven Numbers)
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Conrod bolts may become loose at high engine rpm and cause engine damage. In the event of engine damage, the occurrence of critical riding situations due to escaping oil or engine seizure cannot be precluded.
<b>Remedial Action</b>	Installing new conrod bolts
<b>Build Dates</b>	01/09/2011 – 05/04/2012
<b>Launch Date</b>	20/04/2012
<b>Tentative Date of Recall Completion</b>	31/10/2012

1	<b>Z029257</b>
2	<b>Z029304</b>
3	<b>Z030758</b>
4	<b>Z031084</b>
5	<b>Z031143</b>
6	<b>Z031144</b>
7	<b>Z031832</b>