

Recall Detail	
<b>Ref No</b>	<b>10000431</b>
<b>Manufacturer</b>	Mitsubishi Motors Corporation
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	Outlander (GF7W)
<b>Dealer (phone no)</b>	Sime Darby Motor Services Limited (Tel: 39138800)
<b>Subject</b>	EPS System
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Due to improper production process of internal circuit element, the power voltage monitoring circuit operates incorrectly, EPS warning lamp may be displayed in combination meter, deactivate power assist function of the EPS, and then increase operating force of the steering.
<b>Remedial Action</b>	Replacement of EPS-ECU.
<b>Build Dates</b>	2013
<b>Launch Date</b>	4/6/2013
<b>Tentative Date of Recall Completion</b>	3/6/2014

1	JMYXTGF7WDZ000101	21	JMYXTGF7WDZ000120
2	JMYXTGF7WDZ000109	22	
3	JMYXTGF7WDZ000108	23	
4	JMYXTGF7WDZ000107	24	
5	JMYXTGF7WDZ000106	25	
6	JMYXTGF7WDZ000102	26	
7	JMYXTGF7WDZ000103	27	
8	JMYXTGF7WDZ000104	28	
9	JMYXTGF7WDZ000105	29	
10	JMYXTGF7WDZ000111	30	
11	JMYXTGF7WDZ000110	31	
12	JMYXTGF7WDZ000113	32	
13	JMYXTGF7WDZ000114	33	
14	JMYXTGF7WDZ000115	34	
15	JMYXTGF7WDZ000116	35	
16	JMYXTGF7WDZ000117	36	
17	JMYXTGF7WDZ000118	37	
18	JMYXTGF7WDZ000119	38	
19	JMYXTGF7WDZ000112	39	
20	JMYXTGF7WDZ000121	40	