| Recall Detail | |
|--|--|
| Ref No | 10000434 |
| Manufacturer | Toyota |
| Vehicle Class | Private Car |
| Model/Type | Prius |
| Dealer (phone no) | Crown Motors Limited (Tel: 2880 4988) |
| Subject | Brake pressure accumulator replacement |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | Due to the insufficient strength of components inside the brake pressure accumulator. There is a possibility that fatigue cracks could be developed in the bellows inside the accumulator due to the vibration of the metal plungers while driving. If this occurs, nitrogen gas in the accumulator could leak into the brake fluid and cause the brake pedal stroke to become longer, resulting in decreased braking force. |
| Remedial Action | Inspect or replace the brake pressure accumulator |
| Build Dates | March 2009 – October 2009 |
| Launch Date | 5 June 2013 |
| Tentative Date of Recall Completion | December 2018 |

| 1 | JTDKN36U005034562 |
|----|-------------------|
| 2 | JTDKN36U005054164 |
| 3 | JTDKN36U101001805 |
| 4 | JTDKN36U301020615 |
| 5 | JTDKN36U405019532 |
| 6 | JTDKN36U405064163 |
| 7 | JTDKN36U501042874 |
| 8 | JTDKN36U505047078 |
| 9 | JTDKN36U601063362 |
| 10 | JTDKN36U601074748 |
| 11 | JTDKN36U701002134 |
| 12 | JTDKN36U705019380 |
| 13 | JTDKN36U801052945 |
| 14 | JTDKN36U905039288 |
| 15 | JTDKN36U905050081 |
| 16 | JTDKN36UX01023253 |
| 17 | JTDKN36UX05005683 |