

Recall Detail	
<b>Ref No</b>	<b>10000455</b>
<b>Manufacturer</b>	Suzuki Motor Corporation
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	SWIFT (AZH412)
<b>Dealer (phone no)</b>	Sime Darby Motor Services Limited (Tel: 39138800)
<b>Subject</b>	Loosen of Torque Converter Bolts
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The bolts of torque converter may become loose and drop off due to insufficient fastening torque. In the worst case, the engine would be stalled and unable to restart.
<b>Remedial Action</b>	Inspect and replace the torque converter bolts if necessary.
<b>Build Dates</b>	26/12/2012 – 01/02/2013
<b>Launch Date</b>	15/01/2014
<b>Tentative Date of Recall Completion</b>	14/01/2015

1	JSAFZC72S00100082	21	
2	JSAFZC72S00100083	22	
3	JSAFZC72S00100084	23	
4	JSAFZC72S00100085	24	
5	JSAFZC72S00100086	25	
6	JSAFZC72S00100087	26	
7	JSAFZC72S00100088	27	
8	JSAFZC72S00100089	28	
9	JSAFZC72S00100090	29	
10	JSAFZC72S00100097	30	
11	JSAFZC72S00100104	31	
12	JSAFZC72S00100105	32	
13	JSAFZC72S00100107	33	
14	JSAFZC72S00100108	34	
15	JSAFZC72S00100110	35	
16	JSAFZC72S00100111	36	
17	JSAFZC72S00100112	37	
18	JSAFZC72S00100113	38	
19	JSAFZC72S00100114	39	
20	JSAFZC72S00100116	40	