

Recall Detail

Ref No	10000472
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Prado
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Replacement of Spiral Cable
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The spiral cable mounted between the steering wheel and steering column transmits electrical signals to components such as steering wheel controls, the horn and the Airbag Assembly. Due to the shape and location of the flexible flat cable's retainer, the flexible flat cable in the spiral cable may be damaged when the steering wheel is turned. When it is damaged, it fails to provide connectivity to the driver's air bag and the air bag warning lamp will illuminate. In addition, the driver's air bag will become deactivated, causing it not to deploy in the event of a crash, increasing the risk of injury.
Remedial Action	Replace the spiral cable
Build Dates	September 2009 - May-2010
Launch Date	14 April 2014
Tentative Date of Recall Completion	December 2014

1	JTEBU9FJ60K000120
2	JTEBU9FJ30K008465
3	JTEBU9FJ70K009103
4	JTEBU9FJ00K009542
5	JTEBU9FJ00K012988
6	JTEBU9FJ40K014341
7	JTEBU9FJ60K016432
8	JTEBU9FJ90K018627