

Recall Detail	
Ref No	10000484
Manufacturer	Suzuki Motor Corporation
Vehicle Class	Private Car
Model/Type	SWIFT (AZH412) / SOLIO (AUI412)
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Loosen of Water Pump Bolts
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Since the fastening force of the bolts that mount the water pump pulley to the water pump is insufficient, there are the bolts loose and abnormal noise occurs. If the vehicle continuous to drive, the bolt might be disengaged, water pump belt comes off, warning light will be lit by poor cooling and power failure. In the worst case, there is a possibility that an engine stops and might not be able to restart again.
Remedial Action	Inspect water pump and replace the bolts.
Build Dates	28/06/2013 – 04/10/2013
Launch Date	08/09/2014
Tentative Date of Recall Completion	07/09/2015

1	JSAFZC72S00100180	20	MA15S228490
2	MA15S224208	21	MA15S228549
3	MA15S224416	22	MA15S228554
4	MA15S224498	23	MA15S228559
5	MA15S224549	24	MA15S228653
6	MA15S224639	25	MA15S228660
7	MA15S224829	26	MA15S228704
8	MA15S224875	27	MA15S229155
9	MA15S225007	28	MA15S229253
10	MA15S227871	29	MA15S229477
11	MA15S227953	30	MA15S229584
12	MA15S227977	31	MA15S229641
13	MA15S228004	32	MA15S229656
14	MA15S228077	33	MA15S229664
15	MA15S228188	34	MA15S229677
16	MA15S228216	35	MA15S229691
17	MA15S228348	36	MA15S229706
18	MA15S228421	37	MA15S229723
19	MA15S228437	38	MA15S229742

39	MA15S229772
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	

79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	
117	
118	