

Recall Detail	
<b>Ref No</b>	<b>10000485</b>
<b>Manufacturer</b>	Mitsubishi Motors Corporation
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	OUTLANDER (CW5W / CW6W)
<b>Dealer (phone no)</b>	Sime Darby Motor Services Limited (Tel: 39138800)
<b>Subject</b>	Brake (stop) lamp out of order
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The brake lamp may not light up due to insufficient conduction caused by the generation of an insulating material at the contact point in the switch. For certain vehicles, it may also cause a phenomenon that the shift lever cannot be shifted from the parking position when the brake lamp does not light up.
<b>Remedial Action</b>	Replace brake stop lamp switch.
<b>Build Dates</b>	2007-2009
<b>Launch Date</b>	11/9/2014
<b>Tentative Date of Recall Completion</b>	10/9/2015

1	JMYXLCW6W8Z001221
2	JMYXLCW6W8Z001270
3	JMYXLCW6W8Z001273
4	JMYXLCW6W8Z001279
5	JMYXLCW6W8Z001283
6	JMYXLCW6W8Z001288
7	JMYXTCW5W7Z000102
8	JMYXTCW5W9Z001277
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	

20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	