

Recall Detail	
<b>Ref No</b>	<b>10000513</b>
<b>Manufacturer</b>	Suzuki Motor Corporation
<b>Vehicle Class</b>	Light Goods Vehicle
<b>Model/Type</b>	EVERY (GE306)
<b>Dealer (phone no)</b>	Sime Darby Motor Services Limited (Tel: 39138800)
<b>Subject</b>	Front Door Latch
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Insufficient strength inside the front door latch during production. If continues to use under this condition, it can break the part resulting in unable lock/unlock the front doors.
<b>Remedial Action</b>	Replace front door latch set.
<b>Build Dates</b>	01/04/2014 – 24/06/2014
<b>Launch Date</b>	11/03/2015
<b>Tentative Date of Recall Completion</b>	10/03/2016

1	DA64V-920560
2	DA64V-920830
3	DA64V-921106
4	DA64V-921376
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	

21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	