| Recall Detail  |   |
|--|---|
| Ref No   | 10000520  |
| Manufacturer   | Renault   |
| Vehicle Class  | Private Car   |
| Model/Type   | CAPTUR  |
| Dealer (phone no)  | 29273555  |
| Subject  | Checking the front flexible brake hose  |
| Progress   | Running   |
| Affected Vehicle Identification Number (VIN)                                       | List as below:  |
| Description of Defect, how it came to light, and possible consequences if ignored. | Risk of damage to front flexible brake hose by the front wheel arch liner. The warning light for a brake fluid level may come on or reduction in brake system efficiency. |
| Remedial Action  | If necessary, replace the front flexible brake hose and wheel arch  |
| Build Dates  | 2014  |
| Launch Date  | 4 May 2015  |
| <b>Tentative Date of Recall Completion</b>   | 31 December 2015  |

| 1 | VF12R401E50767407 |
|---|-------------------|
| 2 | VF12R401E50767415 |
| 3 | VF12R401E50767427 |