

## Recall Detail

<b>Ref No</b>	<b>10000527</b>
<b>Manufacturer</b>	Lexus
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	NX200t
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4922)
<b>Subject</b>	Inspection of ABS Actuator
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The recall involves Anti-Lock Braking system (ABS), Traction Control System (TRAC), and Vehicle Stability Control System (VSC) which are controlled by the ABS actuator. Due to the improper shape of a component inside the ABS actuator, there is a possibility that a resin component could be damaged during its press fitting assembly, creating minute resin fragment(s) which could become stuck in the actuator. If this occurs, the ABS actuator may cause some issues.
<b>Remedial Action</b>	Inspect and if necessary replace the ABS actuator
<b>Build Dates</b>	December 2014 ~ February 2015
<b>Launch Date</b>	27 May 2015
<b>Tentative Date of Recall Completion</b>	December 2017

1	JTJYARBZ102004995
2	JTJYARBZ202005024
3	JTJYARBZ302005047
4	JTJYARBZ502004868
5	JTJYARBZ602005396
6	JTJYARBZ702004788
7	JTJYARBZ702005018
8	JTJYARBZ802004556