

Recall Detail

Ref No	10000538
Manufacturer	Renault
Vehicle Class	Private Car
Model/Type	Clio R.S. 200
Dealer (phone no)	29273555
Subject	Fuel pressure sensor
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Possible fuel leak between the fuel pressure sensor and the injection rail due to an insufficient tightening, would lead to a fuel smell
Remedial Action	Re-tighten the fuel pressure sensor to torque
Build Dates	2013
Launch Date	3 August 2015
Tentative Date of Recall Completion	31 March 2016

1	VF15R4M0E49275897
2	VF15R4M0E49383431
3	VF15R4M0E49383483
4	VF15R4M0E49383485
5	VF15R4M0E49383486
6	VF15R4M0E49383490
7	VF15R4M0E49383491
8	VF15R4M0E49383493
9	VF15R4M0E49383496
10	VF15R4M0E49383499
11	VF15R4M0E49383500
12	VF15R4M0E49383510
13	VF15R4M0E49383522
14	VF15R4M0E49383524
15	VF15R4M0E49383525
16	VF15R4M0E49603570
17	VF15R4M0E49603571
18	VF15R4M0E49603572