

Recall Detail

Ref No	10000573
Manufacturer	Subaru
Vehicle Class	Private Car
Model/Type	Subaru XV
Dealer (phone no)	Motor Image Kowloon Limited (23936118)
Subject	Capacitance-type occupant detection system
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The front passenger plugs a device into the accessory power outlet when the ODS is "ON, and/or when a seated passenger touches a metal part of the vehicle that is electrically grounded – such as the forward/rear seat adjuster lever. This may result in deactivation of the ODS. When this occurs, the Air Bag Warning Light will illuminate and the Passenger Air Bag Indication will be turn "OFF", resulting in a visual warning to the occupant that air bag system is not operating properly.
Remedial Action	Replace new Occupant Control Unit.
Build Dates	2011
Launch Date	11 January 2016
Tentative Date of Recall Completion	31 December 2019

1	JF1GP7KC5CG002508
2	JF1GP7KC5CG002617
3	JF1GP7KC5CG003304
4	JF1GP7KC5CG003471
5	JF1GP7KC5CG003649
6	JF1GP7KC5CG003761
7	JF1GP7KC5CG003790
8	JF1GP7KC5CG003893
9	JF1GP7KC5CG004049
10	JF1GP7KC5CG004214
11	JF1GP7KC5CG004498
12	JF1GP7KC5CG004571
13	JF1GP7KC5CG004627
14	JF1GP7KC5CG004942
15	JF1GP7KC5CG005104
16	JF1GP7KC5CG005224
17	JF1GP7KC5CG005621
18	JF1GP7KC5CG006156
19	JF1GP7KC5CG006269
20	JF1GP7KC5CG006679
21	JF1GP7KC5CG006760