

## Recall Detail

<b>Ref No</b>	<b>10000587</b>
<b>Manufacturer</b>	Lexus
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	ES250
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4922)
<b>Subject</b>	Inspection of Brake Actuator
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	There is a possibility that some brake actuators may have been assembled with a pump containing an O-ring that is damaged in such a way that the brake fluid pressure may not be properly controlled during ABS, TRC and VSC activation.
<b>Remedial Action</b>	Inspect and, if necessary, replace the brake actuator
<b>Build Dates</b>	September 2015 ~ February 2016
<b>Launch Date</b>	6 April 2016
<b>Tentative Date of Recall Completion</b>	December 2017

1	JTHBJ1GG002087738
2	JTHBJ1GG202088258
3	JTHBJ1GG702087932