

Recall Detail	
Ref No.	10000605
Manufacturer	Land Rover
Vehicle Class	N1 – Light Goods Vehicle
Model/Type	Discovery 4
Dealer (phone no. / e-mail)	British Motors Limited - (Tel: 2821 7100 or 2820 5150 / service@landrover.com.hk)
Subject	Crankshaft Position Sensor
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	A defective crankshaft position sensor may cause poor engine performance which in turn affects the vehicle control in extremely rare condition
Remedial Action	Replace new crankshaft position sensor
Build Dates	2012 to 2013
Launch Date	28 July 2016
Tentative Date of Recall Completion	31 December 2022

1. SALLAAAG5CA632152
2. SALLAAAG5CA632383
3. SALLAAAG5CA632671
4. SALLAAAG5CA634345
5. SALLAAAG5CA635458
6. SALLAAAG5CA638651
7. SALLAAAG5CA641469
8. SALLAAAG5CA641711
9. SALLAAAG5CA642070
10. SALLAAAG5CA645269
11. SALLAAAG5CA646162
12. SALLAAAG5CA647529
13. SALLAAAG5CA648342