

## Recall Detail

|   |  |
|---|--|
| <b>Ref No</b>   | <b>10000662</b>  |
| <b>Manufacturer</b>   | Porsche  |
| <b>Vehicle Class</b>  | Private Car  |
| <b>Model/Type</b>   | 911 (991), 718 (982)   |
| <b>Dealer (phone no)</b>  | 2179 7911  |
| <b>Subject</b>  | Fastening screws for fuel collection pipes   |
| <b>Progress</b>   | <b>Running</b>   |
| <b>Affected Vehicle Identification Number (VIN)</b>                                       | List as below:   |
| <b>Description of Defect, how it came to light, and possible consequences if ignored.</b> | There is a possibility that the fastening screws for the fuel collection pipes on the affected vehicles can shear off due to stress corrosion cracking. If this happens, the high fuel pressure that builds up in the fuel injection system when the engine is running can press the relevant fuel collection pipe off the fuel injectors. This can cause a fuel leak in the engine compartment. |
| <b>Remedial Action</b>  | Replace fastening screws for both fuel collection pipes.   |
| <b>Build Dates</b>  | 2017   |
| <b>Launch Date</b>  | 07-March-2017  |
| <b>Tentative Date of Recall Completion</b>  | 07-March-2017  |

|     |                   |
|-----|-------------------|
| 1.  | WP0ZZZ98ZHS210110 |
| 2.  | WP0ZZZ98ZHS210140 |
| 3.  | WP0ZZZ98ZHS210633 |
| 4.  | WP0ZZZ98ZHS210847 |
| 5.  | WP0ZZZ98ZHS230124 |
| 6.  | WP0ZZZ98ZHS230217 |
| 7.  | WP0ZZZ98ZHS230689 |
| 8.  | WP0ZZZ98ZHS230710 |
| 9.  | WP0ZZZ98ZHS230739 |
| 10. | WP0ZZZ98ZHS230740 |
| 11. | WP0ZZZ98ZHS230741 |
| 12. | WP0ZZZ98ZHS230748 |
| 13. | WP0ZZZ98ZHS230749 |
| 14. | WP0ZZZ98ZHS230751 |
| 15. | WP0ZZZ98ZHS230752 |
| 16. | WP0ZZZ98ZHS230801 |
| 17. | WP0ZZZ99ZHS100312 |
| 18. | WP0ZZZ99ZHS100482 |
| 19. | WP0ZZZ99ZHS100582 |
| 20. | WP0ZZZ99ZHS100602 |

|     |                   |
|-----|-------------------|
| 21. | WP0ZZZ99ZHS100781 |
| 22. | WP0ZZZ99ZHS100812 |
| 23. | WP0ZZZ99ZHS110632 |
| 24. | WP0ZZZ99ZHS110637 |
| 25. | WP0ZZZ99ZHS110929 |
| 26. | WP0ZZZ99ZHS110934 |
| 27. | WP0ZZZ99ZHS110955 |
| 28. | WP0ZZZ99ZHS110958 |
| 29. | WP0ZZZ99ZHS110962 |
| 30. | WP0ZZZ99ZHS110990 |
| 31. | WP0ZZZ99ZHS111156 |
| 32. | WP0ZZZ99ZHS111182 |
| 33. | WP0ZZZ99ZHS111185 |
| 34. | WP0ZZZ99ZHS111737 |
| 35. | WP0ZZZ99ZHS111831 |
| 36. | WP0ZZZ99ZHS111832 |
| 37. | WP0ZZZ99ZHS111840 |
| 38. | WP0ZZZ99ZHS111849 |
| 39. | WP0ZZZ99ZHS111985 |
| 40. | WP0ZZZ99ZHS112458 |

|     |                   |
|-----|-------------------|
| 41. | WP0ZZZ99ZHS112537 |
| 42. | WP0ZZZ99ZHS112540 |
| 43. | WP0ZZZ99ZHS112552 |
| 44. | WP0ZZZ99ZHS112611 |
| 45. | WP0ZZZ99ZHS112628 |
| 46. | WP0ZZZ99ZHS112985 |
| 47. | WP0ZZZ99ZHS112986 |
| 48. | WP0ZZZ99ZHS112991 |
| 49. | WP0ZZZ99ZHS113014 |
| 50. | WP0ZZZ99ZHS113149 |
| 51. | WP0ZZZ99ZHS113154 |
| 52. | WP0ZZZ99ZHS130108 |
| 53. | WP0ZZZ99ZHS133164 |
| 54. | WP0ZZZ99ZHS138196 |
| 55. | WP0ZZZ99ZHS138466 |
| 56. | WP0ZZZ99ZHS143809 |
| 57. | WP0ZZZ99ZHS144073 |
| 58. | WP0ZZZ99ZHS144348 |
| 59. | WP0ZZZ99ZHS144752 |
| 60. | WP0ZZZ99ZHS144937 |
| 61. | WP0ZZZ98ZHS210625 |
| 62. | WP0ZZZ98ZHS210848 |
| 63. | WP0ZZZ98ZHS210900 |
| 64. | WP0ZZZ99ZHS100669 |
| 65. | WP0ZZZ99ZHS100673 |
| 66. | WP0ZZZ99ZHS101013 |
| 67. | WP0ZZZ99ZHS111047 |
| 68. | WP0ZZZ99ZHS112442 |
| 69. | WP0ZZZ99ZHS143430 |
| 70. | WP0ZZZ99ZHS144472 |
| 71. | WP0ZZZ98ZHS210882 |
| 72. | WP0ZZZ99ZHS112376 |
| 73. | WP0ZZZ99ZHS112650 |