

## Recall Detail

<b>Ref No</b>	<b>10000758</b>
<b>Manufacturer</b>	Lexus
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	GS F/RC F
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4922)
<b>Subject</b>	Replacement of Fuel Pump
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	There is a possibility that the pulsation damper in one of the high pressure fuel pumps could become damaged due to resonance of the fuel pressure under specific operating conditions. This damage can lead to abnormal noise/vibration and, over time, can cause the pump cover to develop a fatigue crack. If the vehicle is operated continuously under these conditions, the crack could expand and fuel may leak.
<b>Remedial Action</b>	Replace the fuel pump
<b>Build Dates</b>	GS F: January 2016 ~ May-2016 RC F: October-2014 ~ August-2015
<b>Launch Date</b>	February 2018
<b>Tentative Date of Recall Completion</b>	December 2018

1	JTHBP1BL20A000866
2	JTHBP1BL50A001882
3	JTHBP1BLX0A001909
4	JTHHP5BC005001735
5	JTHHP5BC005002058
6	JTHHP5BC205004409
7	JTHHP5BC305002510
8	JTHHP5BC405002791
9	JTHHP5BC605000315
10	JTHHP5BC605001805
11	JTHHP5BC605002078
12	JTHHP5BCX05000334