

## Recall Detail

<b>Ref No</b>	<b>10000786</b>
<b>Manufacturer</b>	BMW
<b>Vehicle Class</b>	Passenger Car
<b>Model/Type</b>	M5 (F90)
<b>Dealer (phone no)</b>	31936688
<b>Subject</b>	Reworking the delivery unit fuel line
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below: (Last Seven Numbers)
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The distance of the fuel lines to the fuel level sensor is too small in some cases. Due to that, the fuel level sensor may cause the range to be displayed incorrectly. This may cause the engine to stop running while driving.
<b>Remedial Action</b>	Reposition the fuel lines of the fuel delivery unit
<b>Build Dates</b>	16.01.2018 - 25.06.2018
<b>Launch Date</b>	12/07/2018
<b>Tentative Date of Recall Completion</b>	31/01/2019

1	<b>GA02718</b>
2	<b>GA02719</b>
3	<b>GA02734</b>
4	<b>GA02741</b>
5	<b>GA02748</b>
6	<b>GA02758</b>
7	<b>GA02759</b>
8	<b>GA02762</b>
9	<b>GA02765</b>
10	<b>GA02816</b>
11	<b>GA02937</b>
12	<b>GA02939</b>
13	<b>GA02956</b>
14	<b>GA02965</b>
15	<b>GA02973</b>
16	<b>GA02974</b>
17	<b>GA03002</b>
18	<b>GA03003</b>
19	<b>GA03009</b>
20	<b>GA03010</b>
21	<b>GA03011</b>
22	<b>GA03017</b>

23	<b>GA03057</b>
24	<b>GA03058</b>
25	<b>GA03097</b>
26	<b>GA03098</b>
27	<b>GA03104</b>
28	<b>GA03105</b>
29	<b>GA03140</b>
30	<b>GA03151</b>
31	<b>GA03168</b>
32	<b>GA03169</b>
33	<b>GA03170</b>
34	<b>GA03193</b>
35	<b>GA03260</b>
36	<b>GA03277</b>
37	<b>GA03279</b>
38	<b>GA03286</b>
39	<b>GA03287</b>
40	<b>GA03288</b>
41	<b>GA03290</b>
42	<b>GA03291</b>
43	<b>GA03314</b>
44	<b>GA03343</b>

45	<b>GA03358</b>
46	<b>GA03360</b>
47	<b>GA03362</b>
48	<b>GA03392</b>
49	<b>GA03394</b>
50	<b>GA03396</b>
51	<b>GA03398</b>
52	<b>GA03400</b>
53	<b>GA03408</b>
54	<b>GA03423</b>
55	<b>GA03440</b>
56	<b>GA03465</b>
57	<b>GA03466</b>
58	<b>GA03479</b>
59	<b>GA03482</b>
60	<b>GA03483</b>
61	<b>GA03500</b>
62	<b>GA03503</b>
63	<b>GA03504</b>