| Recall Detail  |  |
|--|--|
| Ref No   | 10000830   |
| Manufacturer   | MINI   |
| Vehicle Class  | Passenger Car  |
| Model/Type   | F56  |
| Dealer (phone no)  | 31936699   |
| Subject  | Replacing exhaust-gas recirculation cooler   |
| Progress   | Running  |
| Affected Vehicle Identification Number (VIN)                                       | List as below: (Last Seven Numbers)  |
| Description of Defect, how it came to light, and possible consequences if ignored. | The exhaust-gas recirculation cooler of the engine may develop leaks over the service life of the vehicle. The escaping coolant could create flammable deposits combined with the soot and oil deposits in the exhaust-gas recirculation cooler. This may lead to localised scorching in the exhaust-gas recirculation cooler. A thermal incident can occur. |
| Remedial Action  | Clean mixing tube and replace exhaust-gas recirculation cooler   |
| Build Dates  | 27.05.2011 - 31.03.2017  |
| Launch Date  | 28/11/2018   |
| Tentative Date of Recall Completion  | 31/05/2019   |

| 1  | 2D25558 |
|----|---------|
| 2  | T736513 |
| 3  | T736514 |
| 4  | T736515 |
| 5  | T736516 |
| 6  | T736517 |
| 7  | T736518 |
| 8  | T736519 |
| 9  | T736520 |
| 10 | T736525 |
| 11 | T736526 |
| 12 | T736531 |
| 13 | T736541 |
| 14 | T736543 |
| 15 | T736545 |
| 16 | T736546 |
|    |         |