

Recall Detail

Ref No	10000832
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	SC430
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Front Passenger Side Airbag Inflator (Re-replacement)
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The passenger side airbag inflator need to be replaced again. It is due to propellant inside the inflator may be degraded after prolonged exposure to high absolute humidity and high temperature. It could cause the inflator to rupture and the front passenger airbag to deploy abnormally in a crash, which could result in increase of the risk of injury to the occupant.
Remedial Action	Replace the front passenger air bag inflator
Build Dates	2000 ~ 2003
Launch Date	December 2018
Tentative Date of Recall Completion	December 2019

1	JTHFN48Y000017036
2	JTHFN48Y100013657
3	JTHFN48Y200032413
4	JTHFN48Y300019881
5	JTHFN48Y400013703
6	JTHFN48Y600015310
7	JTHFN48Y800011131