

## Recall Detail

<b>Ref No</b>	<b>10000833</b>
<b>Manufacturer</b>	Lexus
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	LS500
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4922)
<b>Subject</b>	S&S system reprogram
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	There is a possibility that when the engine restarts within a specific time range after the engine stops, an incorrect intake air volume could be calculated, potentially causing the engine to stall during acceleration from the stationary position.
<b>Remedial Action</b>	Reprogram the S&S system ECU
<b>Build Dates</b>	January 2018 ~ September-2018
<b>Launch Date</b>	December 2018
<b>Tentative Date of Recall Completion</b>	December 2019

1	JTHB5LFF705004393
2	JTHB5LFF405004321
3	JTHB5LFF605002487
4	JTHB5LFF905002466
5	JTHB5LFF205004401
6	JTHB5LFFX05006137
7	JTHB5LFF505003744
8	JTHB5LFF305006089
9	JTHB5LFF005004901
10	JTHB5LFF505002383
11	JTHB5LFF205005189
12	JTHB5LFF705003972
13	JTHB5LFF605003932
14	JTHB5LFF405006005
15	JTHB5LFF005003148
16	JTHB5LFF505003906
17	JTHB5LFF305003080
18	JTHB5LFF405006604
19	JTHB5LFF305004326
20	JTHB5LFFX05004467
21	JTHB5LFF005005000

22	JTHB5LFF305003788
23	JTHB5LFF005002999
24	JTHB5LFF605002781
25	JTHB5LFFX05002900
26	JTHB5LFF305003158
27	JTHB5LFF705004474
28	JTHB5LFF705005964
29	JTHB5LFF605003882
30	JTHB5LFF605002554
31	JTHB5LFF005000556
32	JTHB5LFF105004292
33	JTHB5LFF205003183
34	JTHB5LFF205006651
35	JTHB5LFF405003959
36	JTHB5LFF605004336
37	JTHB5LFF605004837
38	JTHB5LFFX05002976
39	JTHB5LFFX05003870