

Recall Detail

Ref No	10000847
Manufacturer	Mazda Motor Corporation
Vehicle Class	Private Car
Model/Type	Mazda 6
Dealer (phone no)	Vang lek Motors (Hong Kong) Limited 37684848
Subject	Brake assist power may temporarily decreases
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	As the wear resistance performance of the vacuum pump is insufficient, the pump shaft may be worn out with metal powder generated inside the engine. Therefore, the negative pressure generating ability decreases, and when the brake pedal is depressed a plurality in a short time at low engine speed, there is a possibility, in the worst case, the brake assist power will temporarily decrease.
Remedial Action	Replace the vacuum pump with the modified one
Build Dates	March 2013 to May 2013
Launch Date	1/1/2019
Tentative Date of Recall Completion	31/12/2019

1	JM6GJ1021E0121421
2	JM6GJ1021E0121425
3	JM6GJ1021E0121426
4	JM6GJ1021E0121432
5	JM6GJ1021E0121436