

## Recall Detail

<b>Ref No</b>	<b>10000867</b>
<b>Manufacturer</b>	Mazda Motor Corporation
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	MX-5
<b>Dealer (phone no)</b>	Vang lek Motors (Hong Kong) Limited 37684848
<b>Subject</b>	Replacement of undercover
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Due to inappropriate production process, the metal bracket on the undercover may separate from the vehicle while driving. In the worst case, the metal bracket may fall off from the vehicle, creating a road hazard for other users, increasing the risk of a crash.
<b>Remedial Action</b>	Replace the undercover with modified one
<b>Build Dates</b>	1 June, 2015 to 4 July, 2015
<b>Launch Date</b>	29/7/2019
<b>Tentative Date of Recall Completion</b>	29/7/2020

1	JM6ND2E7600100005
2	JM6ND2E7A00100020
3	JM6ND2E7A00100021