

## Recall Detail

<b>Ref No</b>	<b>10000870</b>
<b>Manufacturer</b>	Mazda Motor Corporation
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	CX-9
<b>Dealer (phone no)</b>	Vang lek Motors (Hong Kong) Limited 37684848
<b>Subject</b>	Improve the wiring harnesses at the wire connector terminal
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Due to a change on production process, malfunctions can occur in the passenger frontal air bag system, turn signals, and the engine starting system. In the worst case, the passenger frontal air bags may not deploy when an accident occurs, turn signal lights may become inoperable, and the engine cannot be restarted.
<b>Remedial Action</b>	Improve the wiring harnesses at the wire connector terminal
<b>Build Dates</b>	13 September, 2017 to 16 January, 2018
<b>Launch Date</b>	30/8/2019
<b>Tentative Date of Recall Completion</b>	30/8/2020

1	JM6TC4WLAJ0204283
2	JM6TC4WLAJ0204286
3	JM6TC4WLAJ0204315
4	JM6TC4WLAJ0204339
5	JM6TC4WLAJ0204401
6	JM6TC4WLAJ0205976
7	JM6TC4WLAJ0206023
8	JM6TC4WLAJ0206153
9	JM6TC4WLAJ0206271
10	JM6TC4WLAJ0206432
11	JM6TC4WLAJ0206477
12	JM6TC4WLAJ0206569
13	JM6TC4WLAJ0206624
14	JM6TC4WLAJ0206713
15	JM6TC4WLAJ0206748