

Recall Detail

Ref No	10000871
Manufacturer	Daimler AG
Vehicle Class	Light Goods Vehicle (Van)
Model/Type	G-Class / 461
Dealer (phone no)	Mercedes-Benz Van Authorised Service Centre: 2504 6140 Mercedes-Benz Brand Centre, Kowloon: 2504 6140 Mercedes-Benz Yuen Long Authorised Service Centre: 2504 6140 Mercedes-Benz Fanling Commercial Vehicle Authorised Service Centre: 2637 2988 Mercedes-Benz Hong Kong Limited: 2594 8800
Subject	ABS hydraulic unit brake lines (4290002)
Progress	Running
Affected Vehicle Identification Number (VIN)	Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2): (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. 2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.
Description of Defect, how it came to light, and possible consequences if ignored.	Strong vibrations could occur at the brake lines to the ABS hydraulic unit in affected vehicles as a result of exceptional roadway conditions (washboard roadway). This could cause brake lines to crack. These cracks could cause a minimal amount of leakage in the affected brake circuit. If brake fluid were to escape unnoticed over a longer period of time until the minimum fill level in the expansion reservoir would not be reached, a warning message would be displayed in the instrument cluster. The brake system would remain fully functional in this condition. If this warning were ignored for another long period of time, the braking power of the affected brake circuit could be impaired by a continued brake fluid leakage. This would lead more and more to an increase in the brake pedal travel. In this case, an increased

braking distance and accident hazard cannot be excluded.

Remedial Action

Retrofit affected vehicles with the modified brake lines with optimized routing as a precautionary measure.

Build Dates

02/02/2010 - 21/06/2011

Launch Date

26/08/2019

Tentative Date of Recall Completion

31/12/2019

1	WDB4613332X182493	35	WDB4613332X187169
2	WDB4613332X186336	36	WDB4613332X187192
3	WDB4613332X186348	37	WDB4613332X187204
4	WDB4613332X186393	38	WDB4613332X187245
5	WDB4613332X186399	39	WDB4613332X187334
6	WDB4613332X186405	40	WDB4613332X187372
7	WDB4613332X186420	41	WDB4613332X187427
8	WDB4613332X186427	42	WDB4613332X187433
9	WDB4613332X186433	43	WDB4613332X187458
10	WDB4613332X186442	44	WDB4613332X187492
11	WDB4613332X186450	45	WDB4613332X187499
12	WDB4613332X186462	46	WDB4613332X187518
13	WDB4613332X186475	47	WDB4613332X187523
14	WDB4613332X186484	48	WDB4613332X187542
15	WDB4613332X186502	49	WDB4613332X187555
16	WDB4613332X186510	50	WDB4613332X187572
17	WDB4613332X186529	51	WDB4613332X187580
18	WDB4613332X186537	52	WDB4613332X187595
19	WDB4613332X186545	53	WDB4613332X187605
20	WDB4613332X186776	54	WDB4613332X187615
21	WDB4613332X186785	55	WDB4613332X187624
22	WDB4613332X186800	56	WDB4613332X187637
23	WDB4613332X186806	57	WDB4613332X187648
24	WDB4613332X186815	58	WDB4613332X187681
25	WDB4613332X186830	59	WDB4613332X187692
26	WDB4613332X186842	60	WDB4613332X187702
27	WDB4613332X186851	61	WDB4613332X187712
28	WDB4613332X186862	62	WDB4613332X187721
29	WDB4613332X186870	63	WDB4613332X187740
30	WDB4613332X187033	64	WDB4613332X187758
31	WDB4613332X187068	65	WDB4613332X187768
32	WDB4613332X187076	66	WDB4613332X187788
33	WDB4613332X187108	67	WDB4613332X187813
34	WDB4613332X187161	68	WDB4613332X187821

69	WDB4613332X187866
70	WDB4613332X187942
71	WDB4613332X187954
72	WDB4613332X187995
73	WDB4613332X188012
74	WDB4613332X188040
75	WDB4613332X188070
76	WDB4613332X188114
77	WDB4613332X188132
78	WDB4613332X188159
79	WDB4613332X188305
80	WDB4613332X188350
81	WDB4613332X188389
82	WDB4613332X188434
83	WDB4613332X188460
84	WDB4613332X188466
85	WDB4613332X188487
86	WDB4613332X188495
87	WDB4613332X188524
88	WDB4613332X188531
89	WDB4613332X188562
90	WDB4613332X188570
91	WDB4613332X188586
92	WDB4613332X188589
93	WDB4613332X188599
94	WDB4613332X188608
95	WDB4613332X188617
96	WDB4613332X188634
97	WDB4613332X188661
98	WDB4613332X188688
99	WDB4613332X188695
100	WDB4613332X188716
101	WDB4613332X188725
102	WDB4613332X188737
103	WDB4613332X188765
104	WDB4613332X188773
105	WDB4613332X188777
106	WDB4613332X188786
107	WDB4613332X188793
108	WDB4613332X188810

109	WDB4613332X188842
110	WDB4613332X188845
111	WDB4613332X188873
112	WDB4613332X188893
113	WDB4613332X188953
114	WDB4613332X188963
115	WDB4613332X188991
116	WDB4613332X189020
117	WDB4613332X189043
118	WDB4613332X189068
119	WDB4613332X189101
120	WDB4613332X189121
121	WDB4613332X189128
122	WDB4613332X189202
123	WDB4613332X189234
124	WDB4613332X189275
125	WDB4613332X189290
126	WDB4613332X189306
127	WDB4613332X189321
128	WDB4613332X189338
129	WDB4613332X189362
130	WDB4613332X189393
131	WDB4613332X189490
132	WDB4613332X189529
133	WDB4613332X189551
134	WDB4613332X189589
135	WDB4613332X189601
136	WDB4613332X189645
137	WDB4613332X189682
138	WDB4613332X189719
139	WDB4613332X189754
140	WDB4613332X189799
141	WDB4613332X189976
142	WDB4613332X190007
143	WDB4613332X190037
144	WDB4613332X190143
145	WDB4613332X190176
146	WDB4613332X190216
147	WDB4613332X190265
148	WDB4613332X190317

149	WDB4613332X190504
150	WDB4613332X190543
151	WDB4613332X190567
152	WDB4613332X190578
153	WDB4613332X190607
154	WDB4613332X190958
155	WDB4613332X190999
156	WDB4613332X191028
157	WDB4613332X191039
158	WDB4613332X191048
159	WDB4613332X191081
160	WDB4613332X191110
161	WDB4613332X191129
162	WDB4613332X191163
163	WDB4613332X191187
164	WDB4613332X192190
165	WDB4613432X183239
166	WDB4613432X189414
167	WDB4613432X189633