

Recall Detail

Ref No	10000876
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	SC430
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Front Passenger Side Airbag Inflator (Re-replacement)
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The passenger side airbag inflator need to be replaced again. It is due to propellant inside the inflator may be degraded after prolonged exposure to high absolute humidity and high temperature. It could cause the inflator to rupture and the front passenger airbag to deploy abnormally in a crash, which could result in increase of the risk of injury to the occupant.
Remedial Action	Replace the front passenger air bag inflator
Build Dates	2001 ~ 2009
Launch Date	September 2019
Tentative Date of Recall Completion	December 2020

1	JTHFN45Y409020005
2	JTHFN45Y709014151
3	JTHFN48Y000012967
4	JTHFN48Y200054668
5	JTHFN48Y200058574
6	JTHFN48Y300056820
7	JTHFN48Y400060438
8	JTHFN48Y500067561
9	JTHFN48Y509005461
10	JTHFN48Y600017283
11	JTHFN48Y609000267
12	JTHFN48Y609005419
13	JTHFN48Y709000410
14	JTHFN48Y800012974
15	JTHFN48Y800013199
16	JTHFN48Y800015129
17	JTHFN48Y809003655
18	JTHFN48Y909001641
19	JTHFN48YX00012913
20	JTHFN45Y209015711
21	JTHFN45Y509019980

22	JTHFN45Y909020257
23	JTHFN48Y000027520
24	JTHFN48Y200070031
25	JTHFN48Y400041940
26	JTHFN45Y009021510
27	JTHFN45Y409020974
28	JTHFN45Y709021388
29	JTHFN48Y000011107
30	JTHFN48Y000013391
31	JTHFN48Y200052449
32	JTHFN48Y300049088
33	JTHFN48Y300060589
34	JTHFN48Y600011211
35	JTHFN48Y609005288
36	JTHFN48Y700013288
37	JTHFN48Y800013090
38	JTHFN48Y900065621
39	JTHFN48Y309003675
40	JTHFN48Y600045648
41	JTHFN48Y700049157