

## Recall Detail

<b>Ref No</b>	<b>10000878</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	CLS / 257
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
<b>Subject</b>	Chafe mark on wiring harness of electric coolant pump (2091010)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>The electric line for the power supply of the coolant pump of affected vehicles might get in contact with the engine fan and be subsequently damaged.</p> <p>This might lead to a malfunction of the coolant pump or a deactivation of the 48V on-board electrical system. Subsequently, an engine stall due to too high coolant temperature might occur or the engine would not be able to be restarted after being shut-off by the ECO start/stop or "glide mode" functions, respectively. Both cases would lead to a stalling of the vehicle, increasing the risk of a crash.</p>
<b>Remedial Action</b>	Check on affected vehicles the electric line to the coolant pump for damages and repair it if necessary. Additionally, the routing of the electric line will be modified in order to exclude contact with the engine fan.
<b>Build Dates</b>	09/05/2018 - 24/10/2018
<b>Launch Date</b>	02/10/2019
<b>Tentative Date of Recall Completion</b>	31/12/2019

1	WDD2573591A019465
2	WDD2573592A005189
3	WDD2573592A005418
4	WDD2573592A005564
5	WDD2573592A005634
6	WDD2573592A005650
7	WDD2573592A006182
8	WDD2573592A006214
9	WDD2573592A006746
10	WDD2573592A006770
11	WDD2573592A007009
12	WDD2573592A014570
13	WDD2573592A014574
14	WDD2573592A014580
15	WDD2573592A014612
16	WDD2573592A014623
17	WDD2573592A014639
18	WDD2573592A014692
19	WDD2573592A014727
20	WDD2573592A014760
21	WDD2573592A015012
22	WDD2573592A015292
23	WDD2573592A017788
24	WDD2573592A017908
25	WDD2573592A018191
26	WDD2573592A018378
27	WDD2573592A018546
28	WDD2573592A018592
29	WDD2573592A018700
30	WDD2573592A019078
31	WDD2573592A019519
32	WDD2573592A019605
33	WDD2573592A019720
34	WDD2573592A020548
35	WDD2573592A021473
36	WDD2573592A021490
37	WDD2573592A022149
38	WDD2573592A022215
39	WDD2573592A022216
40	WDD2573592A022224

41	WDD2573592A022273
42	WDD2573592A022344
43	WDD2573592A022348
44	WDD2573592A022350
45	WDD2573592A022361
46	WDD2573592A022363
47	WDD2573592A022365
48	WDD2573592A022542
49	WDD2573592A022543
50	WDD2573592A022971
51	WDD2573592A023011
52	WDD2573592A023085
53	WDD2573592A023143
54	WDD2573592A023163
55	WDD2573592A023185
56	WDD2573592A023743
57	WDD2573592A023852
58	WDD2573592A023859
59	WDD2573592A023876
60	WDD2573592A025160
61	WDD2573592A025657
62	WDD2573592A025671
63	WDD2573592A025778
64	WDD2573592A025916
65	WDD2573592A026224
66	WDD2573592A026239
67	WDD2573592A026316
68	WDD2573592A026552
69	WDD2573592A026678
70	WDD2573592A026730
71	WDD2573592A026854
72	WDD2573592A026980
73	WDD2573592A026989
74	WDD2573592A027060
75	WDD2573592A027160
76	WDD2573592A027258
77	WDD2573592A029177
78	WDD2573592A029318