

## Recall Detail

<b>Ref No</b>	<b>10000914</b>
<b>Manufacturer</b>	Mazda Motor Corporation
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	Mazda3
<b>Dealer (phone no)</b>	Vang lek Motors (Hong Kong) Limited 3768 4848
<b>Subject</b>	Automatic engine restart fail
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	On certain vehicles, the inappropriate programming of the idling engine restart software may cause the engine fail to restart after idling has been stopped. In the worst case, drivers need to restart the vehicle through normal engine start procedure.
<b>Remedial Action</b>	Reprogram the Powertrain Control Module.
<b>Build Dates</b>	6 <sup>th</sup> May, 2019 to 1 <sup>st</sup> November, 2019
<b>Launch Date</b>	10/01/2020
<b>Tentative Date of Recall Completion</b>	10/01/2021

1	JM6BP2S7AK1102899
2	JM6BP2H7AK1103055
3	JM6BP2H7AK1103079
4	JM6BP2H7AL1103609
5	JM6BP2S7AL1103642
6	JM6BP2H7AL1103670
7	JM6BP2S7AL1103682
8	JM6BP2H7AL1103739
9	JM6BP2S7AL1103751
10	JM6BP2H7AL1103776
11	JM6BP2H7AL1103807
12	JM6BP2H7AL1103819
13	JM6BP2H7AL1103956
14	JM6BP2S7AL1103996
15	JM6BP2H7AL1104020
16	JM6BP2S7AK1103038