

## Recall Detail

<b>Ref No</b>	<b>10000948</b>
<b>Manufacturer</b>	Honda
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	ODYSSEY RC1
<b>Dealer (phone no)</b>	22168183
<b>Subject</b>	Replace Seat Belt Kit
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The rear seat belt assemblies installed on affected vehicles have dual locking mechanisms that operate independently of one another to lock the seat belt: the vehicle sensor, which engages during vehicle deceleration, and the webbing sensor, which engages during rapid seat belt extension. Due to incorrect manufacturing of the rear seat belt assembly, the webbing sensor in the assembly could become inoperative and, if the vehicle sensor fails to engage during a crash, proper restraint may not be provided to a belted occupant, increasing the risk of an injury.
<b>Remedial Action</b>	Replace Seat Belt Kit
<b>Build Dates</b>	2019
<b>Launch Date</b>	06 JUL 2020
<b>Tentative Date of Recall Completion</b>	06 JUL 2027

JHMRC1830KC205132

JHMRC1830KC205133

JHMRC1830KC205135

JHMRC1830KC205137

JHMRC1850KC205130

JHMRC1850KC205131

JHMRC1850KC205160

JHMRC1850KC205161