

Recall Detail

Ref No	10000950
Manufacturer	Honda
Vehicle Class	Private Car
Model/Type	VEZEL RU1
Dealer (phone no)	22168183
Subject	Replace Seat Belt Kit
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The rear seat belt assemblies installed on affected vehicles have dual locking mechanisms that operate independently of one another to lock the seat belt: the vehicle sensor, which engages during vehicle deceleration, and the webbing sensor, which engages during rapid seat belt extension. Due to incorrect manufacturing of the rear seat belt assembly, the webbing sensor in the assembly could become inoperative and, if the vehicle sensor fails to engage during a crash, proper restraint may not be provided to a belted occupant, increasing the risk of an injury.
Remedial Action	Replace Seat Belt Kit
Build Dates	2020
Launch Date	06 JUL 2020
Tentative Date of Recall Completion	06 JUL 2027

JHMRU1850LX207809
 JHMRU1850LX207810
 JHMRU1850LX207811
 JHMRU1850LX207812
 JHMRU1850LX207813
 JHMRU1850LX208008
 JHMRU1850LX208011
 JHMRU1850LX208012
 JHMRU1850LX208013
 JHMRU1850LX208014
 JHMRU1850LX208217
 JHMRU1850LX208218
 JHMRU1850LX208219
 JHMRU1850LX208220
 JHMRU1850LX208221
 JHMRU1850LX208223
 JHMRU1850LX208224