

## Recall Detail

<b>Ref No</b>	<b>10001004</b>
<b>Manufacturer</b>	Kia
<b>Vehicle Class</b>	Car
<b>Model/Type</b>	SORENTO(BL) and CARNIVAL(VQ)
<b>Dealer (phone no)</b>	2462 4621
<b>Subject</b>	ABS PCB Relay Block Kit Installation
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Oil or water entering into the power supply of the ABS module over a long period of time Some vehicles might experience the electrical short on the ABS/ESC module power
<b>Remedial Action</b>	Install the ABS PCB relay block kit
<b>Build Dates</b>	BL: From Dec. 14, 2005 through Dec. 17, 2008 VQ: From Jun. 10, 2005 through Dec. 14, 2009
<b>Launch Date</b>	Jun. 17, 2020
<b>Tentative Date of Recall Completion</b>	Dec. 2024

KNAMB752396285393	KNEMB752376108291
KNAMB752396285394	KNEMB752376175650
KNAMB752396285395	KNEMB752376175651
KNAMB752396289390	KNEMB752376184921
KNAMB752396289391	KNEMB752376184922
KNAMB752396289392	KNEMB752386210310
KNAMB752396289393	KNEMB752386218632
KNAMB752396289394	KNEMB752386218633
KNAMB752396307544	KNEMB752386276002
KNAMB754396295016	KNEMB752386277653
KNEMB752366088248	KNEMB752386277654
KNEMB752366088249	
KNEMB752366088250	
KNEMB752366088251	
KNEMB752366088252	
KNEMB752376108286	
KNEMB752376108287	
KNEMB752376108288	
KNEMB752376108289	
KNEMB752376108290	