

## Recall Detail

<b>Ref No</b>	<b>10001010</b>
<b>Manufacturer</b>	Bentley
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	Flying Spur
<b>Dealer (phone no)</b>	Ap Lei Chau Service Center Tel: 25537713 Tsuen Wan Service Center Tel: 21119679 Kowloon Bay Service Center Tel: 22621288
<b>Subject</b>	Knee Airbag Wiring incorrect terminal cavity locations
<b>Progress</b>	In process
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	It is possible for driver's knee roll airbag will not deploy but the passenger side knee roll airbag will deploy during the event of an accident.
<b>Remedial Action</b>	Correct the wiring in the airbag control module connector.
<b>Build Dates</b>	Model Year: From 2020 to 2021
<b>Launch Date</b>	13 May 2021
<b>Tentative Date of Recall Completion</b>	13 May 2023

1	SCBBA53S2LC079144	20	SCBBS53S8LC081848
2	SCBBA53SXLC079182	21	SCBBS53S5LC082097
3	SCBBA53S6LC079843	22	SCBBS53S9LC082121
4	SCBBA53S0LC081104	23	SCBBS53S9LC082782
5	SCBBA53S4LC082398	24	SCBBS53S0LC083755
6	SCBBX53S8MC084994	25	SCBBS53S5LC084058
7	SCBBA53S8LC079150	26	SCBBS53S0LC084470
8	SCBBS53S6LC079161	27	SCBBS53S8LC084488
9	SCBBS53S7LC079167	28	SCBBS53S3LC084530
10	SCBBS53S6LC079175	29	SCBBS53S6LC084599
11	SCBBS53SXLC079180	30	SCBBX53S1MC084996
12	SCBBS53S4LC079191	31	SCBBS53S4LC079319
13	SCBBS53S6LC079323	32	SCBBS53S1LC079553
14	SCBBS53S0LC079561	33	SCBBS53S3LC080395
15	SCBBS53S3LC079974	34	SCBBS53SXLC080698
16	SCBBS53S4LC079997	35	SCBBS53S7LC081727
17	SCBBS53S5LC080270	36	SCBBS53SXLC081821
18	SCBBS53S3LC080316	37	SCBBS53S9LC081860
19	SCBBS53S7LC080979	38	SCBBS53SXLC081883
		39	SCBBS53SXLC081902

40	SCBBS53S6LC081914
41	SCBBS53S6LC082027
42	SCBBS53SXLC083312
43	SCBBS53S3LC083443
44	SCBBS53S6LC083498
45	SCBBS53S8LC083499
46	SCBBS53S0LC083626
47	SCBBS53S8LC083633
48	SCBBS53S2LC083689
49	SCBBS53S1LC083697
50	SCBBS53S3LC083734
51	SCBBS53S8LC083888
52	SCBBX53S9MC085264