

Recall Detail	
<b>Ref No</b>	10001064
<b>Manufacturer</b>	Lexus
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	NX (AAZH20)
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4130)
<b>Subject</b>	Display audio reprogram
<b>Progress</b>	Running
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Due to an error in the software of display audio (control program), display audio cannot switch the screen image on display audio monitor correctly when changing the shift position or detecting vehicle speed pulse. Therefore, video image might be kept displaying on display audio monitor while driving unintentionally.
<b>Remedial Action</b>	Reprogram audio module
<b>Build Dates</b>	29 Nov 2021 to 11 Mar 2022
<b>Launch Date</b>	28 April 2022
<b>Tentative Date of Recall Completion</b>	31 Dec 2024

1	JTJCDDAZ202002016
2	JTJCDDAZ302002042
3	JTJCDDAZ802002182
4	JTJCDDAZ302002073
5	JTJCDDAZ402002261
6	JTJCDDAZ802002182
7	JTJCDDAZ802002618