

| Recall Detail  |  |
|--|--|
| Ref No   | 10001071   |
| Manufacturer   | Rolls-Royce  |
| Vehicle Class  | Passenger Car  |
| Model/Type   | Ghost  |
| Dealer (phone no)  | 31936999   |
| Subject  | Auxiliary water pump replacement   |
| Progress   | Running  |
| Affected Vehicle Identification Number (VIN)                                       | List as below: (Last Seven Numbers)  |
| Description of Defect, how it came to light, and possible consequences if ignored. | Auxiliary water pump's electronic circuit board may malfunction, it can lead to the auxiliary water pump overheated. |
| Remedial Action  | Replace the auxiliary water pump   |
| Build Dates  | 15-10-2010 – 19-08-2011  |
| Launch Date  | 08-10-2021   |
| Tentative Date of Recall Completion  | 08-10-2022   |

|   |         |
|---|---------|
| 1 | UH15123 |
| 2 | UH15252 |
| 3 | UH15219 |
| 4 | UH15293 |
| 5 | UH15528 |
| 6 | UH15134 |
| 7 | UH15196 |
| 8 | UH15323 |