| Recall Detail | |
|--|---|
| Ref No | 10001119 |
| Manufacturer | HINO |
| Vehicle Class | Heavy Goods Vehicle |
| Model/Type | Hino 700 series FY1EUKH-DSAPEA |
| Dealer (phone no) | Crown Motors Limited (Tel: 2841 8520/ 2828 4545) |
| Subject | Wiring harness fixing boss |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | The wiring harness fixing boss which is welded on R1 axle housing may interfere with lateral rod in certain severe operation environment. In the worst case scenario, lateral rod may have damaged by hitting with the boss frequently, then stability will be reduced if the lateral rod has broken finally. This may lead to an accident risk for the occupant and other road users. Therefore, relocate the wiring harness fixing boss on R1 axle housing. Also replace the lateral rod and/or R1 axle housing depend on the damage condition. |
| Remedial Action | Install extended parts on the wheel guard. |
| Build Dates | April 2020 - June 2022 |
| Launch Date | May 2023 |
| Tentative Date of Recall Completion | 30 Dec 2024 |

| 1 | JHDFY1EUKXXX14581 |
|---|-------------------|
| 2 | JHDFY1EUKXXX14591 |
| 3 | JHDFY1EUKXXX14610 |
| 4 | JHDFY1EUKXXX14620 |
| 5 | JHDFY1EUKXXX14657 |
| 6 | JHDFY1EUKXXX14674 |