

## Recall Detail

<b>Ref No</b>	<b>10001146</b>
<b>Manufacturer</b>	Subaru
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	SUBARU BRZ
<b>Dealer (phone no)</b>	Motor Image Kowloon Limited (23936118)
<b>Subject</b>	Rear turn signal illumination failure
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The cause of the failure is the reduction of the voltage applied to the LED due to the inappropriate design of the control circuit of the rear combination lamp.
<b>Remedial Action</b>	For all the affected vehicles, Subaru dealers will replace the rear combination lamps with countermeasure parts on both sides.
<b>Build Dates</b>	2022-2023
<b>Launch Date</b>	1st December 2023
<b>Tentative Date of Recall Completion</b>	31 <sup>st</sup> December 2024

VIN	
1 JF1ZD8K81NG002086	12 JF1ZD8K81NG002281
2 JF1ZD8K72NG002084	13 JF1ZD8K81NG002284
3 JF1ZD8K72NG002190	14 JF1ZD8K81NG002288
4 JF1ZD8K72NG002197	15 JF1ZD8K81NG002285
5 JF1ZD8K81NG002242	16 JF1ZD8K81NG002297
6 JF1ZD8K81NG002244	17 JF1ZD8K81NG002304
7 JF1ZD8K81NG002254	18 JF1ZD8K81NG002307
8 JF1ZD8K81NG002258	19 JF1ZD8K81NG002314
9 JF1ZD8K81NG002262	20 JF1ZD8K81NG002318
10 JF1ZD8K81NG002265	21 JF1ZD8K81NG002327
11 JF1ZD8K81NG002276	22 JF1ZD8K81NG002331
	23 JF1ZD8K81NG002343

24 JF1ZD8K81NG002347  
25 JF1ZD8K81NG002351  
26 JF1ZD8K81NG002355  
27 JF1ZD8K81NG002429  
28 JF1ZD8K81NG002361  
29 JF1ZD8K81NG002433  
30 JF1ZD8K81NG002459  
31 JF1ZD8K81NG002467  
32 JF1ZD8K81NG002475  
33 JF1ZD8K81NG002495  
34 JF1ZD8K81NG002499  
35 JF1ZD8K81NG002528  
36 JF1ZD8K81NG002553  
37 JF1ZD8K81NG002570