

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
1		JMYLRN84WYZ000385
2		JMYLRN84WWZ000292
3		JMYLRN84WXZ000181
4		N84W0010888
5		N84W0010902
6		JMYLRN84WWZ000421
7		JMYLRN84WYZ000201
8		JMYLRN84WWZ000436
9		JMYLRN84WWZ000286
10		JMYLRN84WWZ000847
11		JMYLRN84WXZ000842
12	1703	JMYLRN84WWZ000937
13		JMYLRN84WWZ000481
14	BT1378	JMYLRN84WWZ000448
15	HE1972	JMYLRN84WYZ001297
16	FP1119	JMYLRN84WYZ000694
17	GE1300	JMYLRN84WWZ000405
18	HV1011	JMYLRN84WWZ000678
19	FR1707	JMYLRN84WWZ000616
20	KC1680	JMYLRN84WYZ001095
21	DY1738	JMYLRN84WWZ000142
22	HZ1189	JMYLRN84WXZ000440
23	CP1832	JMYLRN84WWZ000322
24	LA1266	JMYLRN84WYZ001186
25	JB1078	JMYLRN84WXZ001042
26	CS183	JMYLRN84WXZ000800
27	KF1293	JMYLRN84WWZ000457
28	FN1482	JMYLRN84W3Z000797
29	LL1554	JMYLRN84WWZ000699
30	ET1778	JMYLRN84WWZ000632

	Reg Mark	Chassis Number
31	CW1323	JMYLRN84W1Z000154
32	KG1529	JMYLRN84WXZ002323
33	FL1987	JMYLRN84WWZ000539
34	HX1992	JMYLRN84WWZ000815
35	GC1808	JMYLRN84WXZ001789
36	HV1162	JMYLRN84WWZ000509
37	KA1333	JMYLRN84WWZ000396
38	BJ1678	JMYLRN84WYZ000813
39	HS1298	JMYLRN84WWZ000280
40	KF1669	JMYLRN84WWZ000931
41	HV1886	JMYLRN84WWZ000654
42	HY1680	JMYLRN84WWZ000238
43	KB1333	JMYLRN84WYZ000908
44	CY1163	JMYLRN84WWZ000102
45	JF1689	JMYLRN84WXZ001864
46	HU1127	JMYLRN84WWZ000465
47	HE1400	JMYLRN84WWZ000939
48	LA1868	JMYLRN84WWZ000915
49	CY1482	JMYLRN84WYZ000882
50	EN1207	JMYLRN84WWZ000167
51	DJ1681	JMYLRN84WWZ000344
52	MH1687	N84W0010221
53	FY1081	JMYLRN84WWZ000716
54	BT1790	JMYLRN84WWZ000330
55	JK1856	JMYLRN84WXZ002319
56	KE1139	JMYLRN84W1Z000135
57	HX1894	JMYLRN84WWZ000841
58	HB1677	JMYLRN84WWZ000444
59	HT1874	JMYLRN84WWZ000180
60	FL115	JMYLRN84W3Z000766

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
61	BH1011	JMYLRN84WWZ000553	91	GY1472	JMYLRN84WXZ001871
62	JF1170	JMYLRN84WXZ002065	92	KC1370	JMYLRN84WWZ000149
63	GJ1250	JMYLRN84WXZ001885	93	FS126	JMYLRN84WWZ000729
64	HX1102	JMYLRN84WWZ000891	94	JA1822	JMYLRN84WXZ001810
65	HL1489	JMYLRN84WWZ000214	95	JX1516	JMYLRN84WWZ000311
66	GA1080	JMYLRN84WXZ002309	96	LG1228	JMYLRN84W3Z000124
67	HW1059	JMYLRN84WWZ000785	97	EK1883	JMYLRN84WXZ000176
68	HA1178	JMYLRN84WWZ000920	98	HY1500	JMYLRN84WWZ000927
69	JU1321	JMYLRN84WXZ001811	99	EV143	JMYLRN84WXZ002079
70	HA1366	JMYLRN84WXZ002125	100	LL1192	JMYLRN84WWZ000147
71	JK1825	JMYLRN84WYZ000652	101	KA1121	JMYLRN84WWZ000634
72	DH182	JMYLRN84WWZ000382	102	GL1018	JMYLRN84WXZ001888
73	HL1680	JMYLRN84WXZ000334	103	HW1368	JMYLRN84WWZ000789
74	HX1484	JMYLRN84WWZ000857	104	JA1738	JMYLRN84WWZ000904
75	FE1081	JMYLRN84WWZ000487	105	EE109	JMYLRN84WWZ000387
76	FJ1938	JMYLRN84WXZ001057	106	EL1121	JMYLRN84WWZ000686
77	BD1828	JMYLRN84WXZ001889	107	HV1537	JMYLRN84WWZ000705
78	FL1689	JMYLRN84WWZ000810	108	MS1028	JMYLRN84WWZ000151
79	GT1048	JMYLRN84WWZ000241	109	EP1887	JMYLRN84WWZ000458
80	HU1741	JMYLRN84WWZ000576	110	GD1163	JMYLRN84WWZ000314
81	CB108	JMYLRN84WYZ000680	111	CR1428	JMYLRN84WXZ001675
82	DV1298	JMYLRN84WWZ000582	112	DK1971	JMYLRN84WXZ000819
83	HU1509	JMYLRN84WWZ000522	113	LY1656	JMYLRN84WXZ001531
84	DS1186	JMYLRN84WXZ002059	114	FH166	JMYLRN84WWZ000331
85	JW1262	JMYLRN84WWZ000728	115	XX20	JMYLRN84WYZ001051
86	HT182	JMYLRN84WWZ000306	116	KH2065	JMYLRN84WYZ001417
87	JX1980	JMYLRN84WWZ000158	117	HZ2321	JMYLRN84WWZ000201
88	JF1920	JMYLRN84WXZ001852	118	FX237	JMYLRN84WXZ000832
89	HN1820	JMYLRN84WWZ000725	119	HT206	JMYLRN84WWZ000257
90	HB1777	JMYLRN84WWZ000307	120	DJ2982	JMYLRN84WXZ001830

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
121	GS2162	JMYLRN84WWZ000318	151	BR2383	JMYLRN84WWZ000516
122	KG2071	JMYLRN84WYZ001416	152	DF2698	JMYLRN84WWZ000472
123	JH2917	JMYLRN84WXZ001900	153	LP265	JMYLRN84WWZ000216
124	HT2805	JMYLRN84WWZ000350	154	DR2823	JMYLRN84WWZ000691
125	KL2554	JMYLRN84W2Z000443	155	GL2879	JMYLRN84WXZ001519
126	JD2468	JMYLRN84WXZ001182	156	JC2303	JMYLRN84WXZ001403
127	KB2352	JMYLRN84WWZ000597	157	KE2918	JMYLRN84WYZ000990
128	JC2176	JMYLRN84WXZ001099	158	LJ2165	JMYLRN84WWZ000882
129	LA2196	JMYLRN84W3Z000916	159	EV2306	JMYLRN84WXZ000194
130	JD2030	JMYLRN84WYZ000714	160	AT22	JMYLRN84WXZ002072
131	GS2919	JMYLRN84WXZ002116	161	JH2604	JMYLRN84WXZ002300
132	CT2506	JMYLRN84WYZ000711	162	KZ2676	JMYLRN84WWZ000703
133	HZ2355	JMYLRN84WXZ000243	163	HV2670	JMYLRN84WWZ000679
134	HU2007	JMYLRN84WWZ000628	164	AT289	JMYLRN84WWZ000449
135	JF2029	JMYLRN84WXZ001823	165	DP2225	JMYLRN84WYZ000995
136	HU2989	JMYLRN84WWZ000309	166	HT2620	JMYLRN84WWZ000267
137	HW2901	JMYLRN84WWZ000791	167	JF2221	JMYLRN84WYZ000932
138	HT2900	JMYLRN84WWZ000262	168	JB2832	JMYLRN84WXZ001155
139	JU2521	JMYLRN84WWZ000397	169	JA2006	JMYLRN84WXZ000818
140	HP246	JMYLRN84WXZ001875	170	JH2808	JMYLRN84WWZ000279
141	EP2999	JMYLRN84WWZ000742	171	HZ2939	JMYLRN84WXZ000323
142	GL2805	JMYLRN84WWZ000643	172	JE2816	JMYLRN84WXZ002091
143	JJ2799	JMYLRN84WXZ002135	173	DG258	JMYLRN84WWZ000589
144	EH235	JMYLRN84WWZ000507	174	JS2300	JMYLRN84WWZ000548
145	HV2997	JMYLRN84WWZ000726	175	HS2761	JMYLRN84WWZ000128
146	JM2178	JMYLRN84WXZ002301	176	HU2260	JMYLRN84WWZ000437
147	GS2488	JMYLRN84WYZ000672	177	JA2818	JMYLRN84WXZ000322
148	KX293	JMYLRN84WWZ000136	178	KD2885	JMYLRN84WWZ000441
149	GK2884	JMYLRN84WWZ000210	179	JD2201	JMYLRN84WXZ001561
150	JB2930	JMYLRN84WXZ000376	180	FR2137	JMYLRN84WWZ000188

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
181	JN235	JMYLRN84WXZ002123
182	JM2505	JMYLRN84WYZ000203
183	LV2622	JMYLRN84WWZ000498
184	HU2038	JMYLRN84WWZ000610
185	HY225	JMYLRN84WWZ000929
186	KR2709	JMYLRN84WWZ000602
187	BZ2298	JMYLRN84WWZ000483
188	KL2166	JMYLRN84WWZ000917
189	HT2910	JMYLRN84WWZ000354
190	DN2262	JMYLRN84WWZ000334
191	HT2593	JMYLRN84WWZ000206
192	JS2218	JMYLRN84WXZ002325
193	HR2628	JMYLRN84WXZ001095
194	HV273	JMYLRN84WWZ000607
195	BM2002	JMYLRN84WWZ000403
196	GM2832	N84W0010676
197	HT2784	JMYLRN84WWZ000373
198	LJ2296	JMYLRN84WWZ000792
199	JN2177	JMYLRN84WXZ002303
200	LA2142	JMYLRN84WWZ000590
201	HD2787	JMYLRN84WWZ000416
202	KU224	JMYLRN84WWZ000913
203	JA2984	JMYLRN84WXZ000806
204	JN2520	JMYLRN84WWZ000346
205	HU2797	JMYLRN84WWZ000145
206	FZ2018	JMYLRN84WXZ002295
207	KM2691	JMYLRN84WYZ000695
208	AU2808	JMYLRN84WXZ001793
209	HX2291	JMYLRN84WWZ000681
210	GF2220	JMYLRN84WWZ000888

	Reg Mark	Chassis Number
211	KW2468	JMYLRN84WWZ000343
212	JZ2722	JMYLRN84WYZ000698
213	JP2563	JMYLRN84WYZ000862
214	FA207	JMYLRN84WWZ000808
215	LR2821	JMYLRN84WXZ000155
216	JE2528	JMYLRN84WXZ001812
217	GG2954	JMYLRN84W1Z000101
218	KX2959	JMYLRN84W3Z000764
219	JF2900	JMYLRN84WXZ002000
220	DF273	JMYLRN84WWZ000945
221	AS2233	N84W0010402
222	JN2142	JMYLRN84WXZ002289
223	EM3806	JMYLRN84WWZ000172
224	CK339	JMYLRN84WYZ000906
225	FV3389	JMYLRN84WYZ000180
226	BB3836	JMYLRN84WYZ000962
227	LD3009	JMYLRN84WXZ001094
228	KX3309	JMYLRN84W3Z000786
229	HZ3235	JMYLRN84WXZ000240
230	MJ3220	JMYLRN84WYZ001399
231	CK3288	JMYLRN84WWZ000140
232	KN3202	JMYLRN84WYZ001471
233	HT3899	JMYLRN84WWZ000230
234	HU3980	JMYLRN84WWZ000567
235	JB3880	JMYLRN84WXZ000837
236	GZ3652	JMYLRN84WWZ000804
237	JN3526	JMYLRN84W2Z000500
238	CG3345	JMYLRN84W3Z000765
239	JM3794	JMYLRN84WYZ000901
240	EX3080	JMYLRN84WWZ000139

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
241	CA3	JMYLRN84WXZ000228	271	JU362	JMYLRN84WYZ001424
242	KF3943	JMYLRN84W1Z001658	272	HS3830	JMYLRN84WWZ000111
243	HV3708	JMYLRN84WWZ000440	273	LA3159	JMYLRN84WXZ001893
244	LM3967	JMYLRN84WWZ000497	274	HS3372	JMYLRN84WWZ000131
245	KX3711	JMYLRN84W3Z000763	275	FM3063	JMYLRN84WWZ000690
246	JU3052	JMYLRN84W1Z000159	276	XX3807	JMYLRN84WXZ001792
247	CA310	JMYLRN84WXZ001515	277	HS3359	JMYLRN84WWZ000143
248	ES3031	JMYLRN84WYZ001348	278	HT3474	JMYLRN84WWZ000345
249	EC3380	JMYLRN84WXZ001163	279	GU3382	JMYLRN84WWZ000219
250	AW383	JMYLRN84WWZ000190	280	JK371	JMYLRN84WYZ000376
251	FU3038	JMYLRN84WXZ001038	281	KP306	JMYLRN84WWZ000763
252	HT3296	JMYLRN84WXZ001872	282	CG3596	JMYLRN84WXZ002252
253	JE3978	JMYLRN84WXZ001807	283	HT316	JMYLRN84WWZ000415
254	GV3829	JMYLRN84WWZ000807	284	KJ3158	JMYLRN84WWZ000525
255	HS3738	JMYLRN84WWZ000571	285	HY3723	JMYLRN84WWZ000941
256	HX3700	JMYLRN84WWZ000834	286	ES312	JMYLRN84WWZ000456
257	JK3605	JMYLRN84WYZ000675	287	243045	JMYLRN84WWZ000316
258	CY3233	JMYLRN84WXZ002256	288	GR324	JMYLRN84WWZ000288
259	HS3892	JMYLRN84WWZ000112	289	MK3540	JMYLRN84WXZ001881
260	JB3618	JMYLRN84WXZ001123	290	LE3715	JMYLRN84WXZ000817
261	LL3843	JMYLRN84WXZ001169	291	HT3106	JMYLRN84WWZ000348
262	JE325	JMYLRN84WXZ001794	292	HZ3632	JMYLRN84WWZ000759
263	DX3263	JMYLRN84WWZ000926	293	MN3198	JMYLRN84WWZ000714
264	LD3714	JMYLRN84WXZ001703	294	HG387	JMYLRN84WWZ000160
265	JN3455	JMYLRN84WYZ001489	295	GP3900	JMYLRN84WXZ001548
266	HA3998	JMYLRN84WYZ001216	296	JL3631	JMYLRN84WYZ000866
267	LD3351	JMYLRN84WWZ000284	297	JB3633	JMYLRN84WWZ000124
268	JP3407	JMYLRN84WYZ001041	298	KX3617	JMYLRN84W3Z000805
269	CH3155	JMYLRN84WYZ000716	299	DP3282	JMYLRN84WWZ000289
270	HS3652	JMYLRN84WWZ000110	300	FU3233	JMYLRN84WXZ000828

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
301	JE3682	JMYLRN84WXZ001799	331	HS3317	JMYLRN84WWZ000105
302	JF331	JMYLRN84WXZ001802	332	JN3899	JMYLRN84WYZ000211
303	JJ3898	JMYLRN84WXZ001903	333	EH377	JMYLRN84WXZ001097
304	AN3323	JMYLRN84WWZ000303	334	HZ3861	JMYLRN84WXZ000280
305	DP3888	JMYLRN84WWZ000523	335	HS3085	JMYLRN84WWZ000122
306	EL392	JMYLRN84WWZ000155	336	JF3009	JMYLRN84WXZ001857
307	HW3863	JMYLRN84WWZ000935	337	HT3539	JMYLRN84WWZ000304
308	HY3634	JMYLRN84WWZ000858	338	DY3310	JMYLRN84WYZ000799
309	CM3633	JMYLRN84WYZ001207	339	KE3484	JMYLRN84WWZ000223
310	JK3633	JMYLRN84WXZ002122	340	FM3002	JMYLRN84WWZ000401
311	AW3338	JMYLRN84WWZ000812	341	GV3014	JMYLRN84WXZ001179
312	AR3888	JMYLRN84WYZ000217	342	KA3577	JMYLRN84WWZ000909
313	KL3919	JMYLRN84W1Z000197	343	HX4849	JMYLRN84WWZ000818
314	KM3545	JMYLRN84WWZ000195	344	HC4881	JMYLRN84W1Z000104
315	JP3880	JMYLRN84WYZ001021	345	JA4292	JMYLRN84WXZ001091
316	KE3435	JMYLRN84WWZ000513	346	HV4638	JMYLRN84WWZ000796
317	EE3273	JMYLRN84WWZ000471	347	FY4688	JMYLRN84WXZ001194
318	JJ3221	JMYLRN84WXZ001991	348	GE4489	JMYLRN84WWZ000266
319	CX3363	JMYLRN84WWZ000126	349	LK4921	JMYLRN84WWZ000107
320	FD3806	JMYLRN84WWZ000594	350	JN4359	JMYLRN84WYZ000700
321	HW3794	JMYLRN84WWZ000821	351	HS4798	JMYLRN84WWZ000189
322	HT3062	JMYLRN84WWZ000380	352	HV4088	JMYLRN84WWZ000693
323	CG3688	JMYLRN84WXZ001052	353	JM4886	JMYLRN84WYZ000844
324	BS3283	JMYLRN84WXZ001132	354	JS4130	JMYLRN84WYZ001036
325	HT3342	JMYLRN84WWZ000320	355	LB4303	JMYLRN84W3Z000942
326	HT3626	JMYLRN84WWZ000236	356	HY4050	JMYLRN84WWZ000754
327	HT3576	JMYLRN84WWZ000360	357	HK49	JMYLRN84WYZ000976
328	HW3109	JMYLRN84WWZ000786	358	HU4128	JMYLRN84WWZ000466
329	GW3930	JMYLRN84WWZ000898	359	MJ4359	JMYLRN84WXZ000213
330	BG338	JMYLRN84W2Z000415	360	LA4255	JMYLRN84WWZ000645

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
361	JZ4301	JMYLRN84W1Z000103
362	LA4220	JMYLRN84WYZ001426
363	KD443	JMYLRN84WWZ000588
364	FP447	JMYLRN84WWZ000749
365	DJ468	JMYLRN84WWZ000508
366	FG4699	JMYLRN84WWZ000205
367	JC4632	JMYLRN84WXZ001190
368	MD4609	JMYLRN84WXZ001874
369	JD4670	JMYLRN84WXZ001634
370	JA4897	JMYLRN84WXZ000820
371	LM4722	JMYLRN84WYZ001210
372	HY416	JMYLRN84WWZ000778
373	FU4570	JMYLRN84WWZ000918
374	BW460	JMYLRN84WXZ001100
375	HS4703	JMYLRN84WWZ000235
376	JD4638	JMYLRN84WXZ001651
377	HW4922	JMYLRN84WWZ000836
378	JE479	JMYLRN84WXZ001832
379	LR4243	JMYLRN84WWZ000584
380	LB4322	JMYLRN84WYZ000909
381	LD4605	JMYLRN84WWZ000366
382	KE439	JMYLRN84WWZ000129
383	JF4509	JMYLRN84WWZ000879
384	JB4405	JMYLRN84WXZ001083
385	KR4682	JMYLRN84WWZ000535
386	HT4442	JMYLRN84WWZ000339
387	KY4866	JMYLRN84WWZ000942
388	JC4889	JMYLRN84WXZ001726
389	GT4383	JMYLRN84WWZ000254
390	KK4675	JMYLRN84WWZ000787

	Reg Mark	Chassis Number
391	HA4633	JMYLRN84WWZ000536
392	HH4590	JMYLRN84WXZ001521
393	KC4039	JMYLRN84WWZ000768
394	LF4367	JMYLRN84WWZ000394
395	HU4628	JMYLRN84WWZ000506
396	KZ4898	JMYLRN84WWZ000805
397	GK403	JMYLRN84WXZ001149
398	JD440	JMYLRN84WXZ001840
399	JW4979	JMYLRN84WWZ000301
400	KD4750	JMYLRN84WYZ001244
401	HT4327	JMYLRN84WWZ000370
402	JC428	JMYLRN84WXZ000400
403	JX4005	JMYLRN84WYZ001240
404	HY403	JMYLRN84WWZ000682
405	HZ4591	JMYLRN84WXZ000301
406	LU4043	JMYLRN84WWZ000623
407	KE4215	JMYLRN84WYZ000987
408	JG4177	JMYLRN84WWZ000558
409	GT4028	JMYLRN84WXZ001173
410	JU4698	JMYLRN84WYZ001064
411	KD4387	JMYLRN84WWZ000418
412	KN4111	JMYLRN84WWZ000561
413	FT4080	N94W0020038
414	JC4925	JMYLRN84WXZ001193
415	JA4776	JMYLRN84WXZ000358
416	HV4404	JMYLRN84WWZ000673
417	JG493	JMYLRN84WXZ002321
418	JP420	JMYLRN84WXZ002258
419	HY5493	JMYLRN84WWZ000709
420	KH528	JMYLRN84WXZ002331

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
421	FT5851	JMYLRN84WXZ000401
422	LS576	JMYLRN84WYZ000910
423	HS5329	JMYLRN84WWZ000198
424	JL5491	JMYLRN84WYZ000800
425	GA5479	JMYLRN84WWZ000545
426	HU5859	JMYLRN84WWZ000480
427	KL5432	JMYLRN84W2Z000423
428	KE5190	JMYLRN84WYZ001427
429	EP599	JMYLRN84WXZ000202
430	JL5684	JMYLRN84WYZ000715
431	HW5259	JMYLRN84WWZ000670
432	ED5698	JMYLRN84WYZ000816
433	CK5114	JMYLRN84WWZ000631
434	HU5071	JMYLRN84WWZ000117
435	LK5916	JMYLRN84WWZ000520
436	LX5081	JMYLRN84WXZ000349
437	HU5888	JMYLRN84WWZ000463
438	HX5140	JMYLRN84WWZ000876
439	HV5165	JMYLRN84WWZ000591
440	JR5074	JMYLRN84WWZ000510
441	JW5060	JMYLRN84WWZ000560
442	HU5993	JMYLRN84WWZ000528
443	HV5532	JMYLRN84WWZ000755
444	HU5610	JMYLRN84WWZ000399
445	JP590	JMYLRN84WYZ001289
446	JB5091	JMYLRN84WXZ001148
447	JZ5699	JMYLRN84WWZ000412
448	MJ5176	JMYLRN84W3Z000802
449	HV5108	JMYLRN84WWZ000680
450	HY5624	JMYLRN84WWZ000402

	Reg Mark	Chassis Number
451	JM5053	JMYLRN84WYZ001231
452	HW5737	JMYLRN84WWZ000823
453	KS5213	JMYLRN84W3Z000105
454	KX5943	JMYLRN84W3Z000804
455	HU5059	JMYLRN84WWZ000519
456	LJ5172	JMYLRN84WXZ001834
457	KX5062	JMYLRN84W3Z000795
458	EF568	JMYLRN84WXZ000222
459	JA5254	JMYLRN84WXZ000804
460	LT5465	JMYLRN84WWZ000551
461	JJ5341	JMYLRN84WXZ002088
462	LZ5569	JMYLRN84WWZ000579
463	JD5421	JMYLRN84WWZ000153
464	JX5207	JMYLRN84WXZ001603
465	XX521	JMYLRN84WWZ000489
466	HT5004	JMYLRN84WWZ000227
467	HT562	JMYLRN84WWZ000146
468	KU5591	JMYLRN84WXZ001098
469	JG5178	JMYLRN84WXZ001850
470	FV5610	JMYLRN84WWZ000866
471	LH512	JMYLRN84WWZ000278
472	JL5975	JMYLRN84WYZ000688
473	KF5243	JMYLRN84W1Z001657
474	KF5715	JMYLRN84W1Z001745
475	HV5998	JMYLRN84WWZ000795
476	JA5197	JMYLRN84WXZ000238
477	LE5707	JMYLRN84WXZ000158
478	LP5798	JMYLRN84WXZ002306
479	JE5508	JMYLRN84WXZ001841
480	HY597	JMYLRN84WWZ000757

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
481	FF5195	JMYLRN84WWZ000477	511	LL6279	JMYLRN84WWZ000261
482	LR553	JMYLRN84WWZ000114	512	GZ661	JMYLRN84WWZ000351
483	KY5756	JMYLRN84WWZ000182	513	GU6676	JMYLRN84WWZ000476
484	FB5611	JMYLRN84WWZ000166	514	DG6872	JMYLRN84WXZ002103
485	FS5377	JMYLRN84WYZ001480	515	LR6609	JMYLRN84WXZ001516
486	KN5223	JMYLRN84WXZ001370	516	FV6823	JMYLRN84WWZ000256
487	JU6716	JMYLRN84WYZ001195	517	HY6586	JMYLRN84WXZ000182
488	HW6030	JMYLRN84WWZ000756	518	HE6863	JMYLRN84WWZ000165
489	FY6306	JMYLRN84W1Z000102	519	FV6371	JMYLRN84W2Z000431
490	DC6606	JMYLRN84WWZ000603	520	HV6353	JMYLRN84WWZ000668
491	JE6610	JMYLRN84WYZ001080	521	FY601	JMYLRN84WWZ000609
492	HX6182	JMYLRN84WWZ000765	522	JF6843	JMYLRN84WXZ001895
493	GW6313	JMYLRN84WWZ000260	523	EU6277	JMYLRN84WXZ001598
494	JC6380	JMYLRN84WXZ001137	524	HV6325	JMYLRN84WWZ000794
495	FD6613	JMYLRN84WXZ000298	525	GM695	JMYLRN84WXZ002310
496	KU6887	JMYLRN84WXZ001101	526	GB6819	JMYLRN84WWZ000600
497	KM643	JMYLRN84WWZ000694	527	HS6406	JMYLRN84WWZ000207
498	GS6687	JMYLRN84WWZ000349	528	HU6234	JMYLRN84WWZ000383
499	HA635	JMYLRN84WWZ000629	529	HT6639	JMYLRN84WWZ000502
500	LD6119	JMYLRN84WXZ001680	530	CC629	JMYLRN84WWZ000239
501	HX6071	JMYLRN84WWZ000896	531	GT629	JMYLRN84WWZ000635
502	LD6345	JMYLRN84W1Z001738	532	LB6734	JMYLRN84WXZ000803
503	LA651	JMYLRN84W3Z000926	533	KY6238	JMYLRN84WWZ000123
504	FZ6282	JMYLRN84WWZ000247	534	GM619	JMYLRN84WXZ001152
505	EF6632	JMYLRN84WYZ000645	535	KP647	JMYLRN84W2Z000520
506	FE681	JMYLRN84WXZ001104	536	JM639	JMYLRN84WYZ001247
507	JB651	JMYLRN84WWZ000744	537	HS6098	JMYLRN84WWZ000211
508	FB6966	JMYLRN84WWZ000895	538	BW6759	JMYLRN84WWZ000127
509	JC6026	JMYLRN84WWZ000452	539	HY6187	JMYLRN84WXZ000208
510	GZ6637	JMYLRN84WWZ000564	540	HS6529	JMYLRN84WWZ000293

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
541	EW6800	JMYLRN84WWZ000294	571	CV6696	JMYLRN84WWZ000797
542	FF6839	JMYLRN84WXZ002067	572	FU6669	JMYLRN84WXZ001601
543	JH6659	JMYLRN84WYZ000406	573	HU6682	JMYLRN84WWZ000521
544	JW6712	JMYLRN84WYZ001214	574	HT6798	JMYLRN84WWZ000450
545	GM6654	JMYLRN84WXZ001887	575	HZ6832	JMYLRN84WWZ000723
546	KC6557	JMYLRN84WWZ000120	576	KN6208	JMYLRN84WXZ001688
547	JC6610	JMYLRN84WXZ001536	577	AE6682	JMYLRN84WWZ000365
548	JA6011	JMYLRN84WXZ000831	578	DK662	JMYLRN84WWZ000385
549	JM6433	JMYLRN84WWZ000220	579	JC6377	JMYLRN84WXZ001454
550	GD6863	JMYLRN84WWZ000132	580	JG6817	JMYLRN84WXZ002307
551	FH6555	JMYLRN84WYZ001203	581	HY6603	JMYLRN84WWZ000890
552	HS6522	JMYLRN84WWZ000276	582	HS6663	JMYLRN84WWZ000281
553	FA6186	JMYLRN84WXZ000236	583	JK6112	JMYLRN84WYZ000659
554	EZ602	JMYLRN84WYZ000877	584	JX6038	JMYLRN84WXZ001803
555	DK6993	JMYLRN84WWZ000592	585	HX6845	JMYLRN84WWZ000881
556	HV6431	JMYLRN84WWZ000598	586	EF6698	JMYLRN84WXZ000359
557	JS6808	JMYLRN84WWZ000475	587	HV6800	JMYLRN84WWZ000724
558	JL6103	JMYLRN84WYZ000163	588	KN6796	JMYLRN84WXZ001087
559	FZ6689	JMYLRN84WWZ000556	589	KC6795	JMYLRN84WXZ000843
560	HC6910	JMYLRN84WYZ001190	590	BR639	JMYLRN84WXZ001882
561	GY6989	JMYLRN84WWZ000312	591	JF6240	JMYLRN84WXZ002316
562	EP6263	JMYLRN84WWZ000848	592	JP6210	JMYLRN84WWZ000163
563	GX622	JMYLRN84WWZ000275	593	CL6863	JMYLRN84WWZ000538
564	HT6539	JMYLRN84WWZ000431	594	DP665	JMYLRN84WWZ000800
565	JD6884	JMYLRN84WXZ001818	595	EE6028	JMYLRN84WWZ000259
566	KB6861	JMYLRN84W1Z000164	596	HY620	JMYLRN84WWZ000902
567	JD6870	JMYLRN84WXZ001828	597	GF6286	JMYLRN84WWZ000657
568	KB6098	JMYLRN84WYZ001253	598	HB6843	JMYLRN84WWZ000828
569	HX695	JMYLRN84WWZ000850	599	JB6903	JMYLRN84WWZ000638
570	EX6680	JMYLRN84WWZ000357	600	GH7388	JMYLRN84WWZ000512

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
601	HW7601	JMYLRN84WWZ000809
602	JR7466	N84W0010870
603	HS7027	JMYLRN84WWZ000272
604	ME7286	JMYLRN84W3Z000807
605	JM7661	JMYLRN84WXZ002069
606	FF7088	JMYLRN84WXZ000411
607	HH7866	JMYLRN84WWZ000181
608	JR7800	JMYLRN84WWZ000115
609	JE7351	JMYLRN84WXZ001800
610	HS7315	JMYLRN84WYZ000830
611	HU7298	JMYLRN84WWZ000739
612	GS7872	JMYLRN84WXZ001164
613	GT7	JMYLRN84WYZ000678
614	HT7365	JMYLRN84WWZ000420
615	FG7787	JMYLRN84WXZ000392
616	LD785	JMYLRN84W3Z000936
617	DV7077	JMYLRN84WWZ000750
618	FE7058	JMYLRN84WWZ000298
619	HD782	JMYLRN84WWZ000661
620	HH708	JMYLRN84WWZ000171
621	JB7897	JMYLRN84WXZ001367
622	JW7762	JMYLRN84WWZ000874
623	HT7567	JMYLRN84WWZ000388
624	EX792	JMYLRN84WYZ001197
625	FA7881	N84W0010912
626	GE725	JMYLRN84WYZ000860
627	DD712	JMYLRN84WWZ000738
628	JB7356	JMYLRN84WXZ001129
629	FD7167	JMYLRN84WWZ000113
630	HY7872	JMYLRN84WXZ000154

	Reg Mark	Chassis Number
631	JA7499	JMYLRN84WXZ000829
632	HZ7693	JMYLRN84WXZ000366
633	HU7013	JMYLRN84WWZ000453
634	JP7626	JMYLRN84WWZ000362
635	JE7739	JMYLRN84WXZ002098
636	EN798	JMYLRN84WWZ000485
637	LV7807	JMYLRN84WWZ000851
638	KW7608	JMYLRN84WXZ001107
639	BZ7767	JMYLRN84WWZ000218
640	JB7535	JMYLRN84WXZ001075
641	HV7112	JMYLRN84WWZ000526
642	HF735	JMYLRN84WXZ001134
643	DW733	JMYLRN84WWZ000583
644	KD7163	JMYLRN84WYZ000867
645	DY7555	JMYLRN84WXZ001590
646	HU7159	JMYLRN84WWZ000424
647	HW7345	JMYLRN84WWZ000790
648	JF7451	JMYLRN84WXZ001865
649	HV7336	JMYLRN84WWZ000735
650	HT7099	JMYLRN84WWZ000430
651	HF7882	JMYLRN84WWZ000299
652	HU7083	JMYLRN84WWZ000688
653	JG7340	JMYLRN84WXZ001896
654	CG718	JMYLRN84WWZ000849
655	HS7320	JMYLRN84WWZ000287
656	FA739	JMYLRN84WWZ000352
657	GZ770	JMYLRN84WXZ000258
658	KW7188	JMYLRN84WXZ001140
659	HJ772	JMYLRN84WWZ000244
660	HT7623	JMYLRN84WWZ000455

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
661	LN7916	JMYLRN84WWZ000698	691	JC7962	JMYLRN84WXZ001151
662	FX7627	JMYLRN84WXZ001518	692	HZ709	JMYLRN84WWZ000273
663	JA716	JMYLRN84WXZ000328	693	FB7388	JMYLRN84WXZ000809
664	JD7312	JMYLRN84WXZ001833	694	HU7662	N84W0010900
665	HT7584	JMYLRN84WWZ000445	695	HT7346	JMYLRN84WWZ000460
666	LT7163	JMYLRN84WWZ000329	696	KZ769	N84W0010896
667	AV795	JMYLRN84WWZ000191	697	DW844	JMYLRN84WWZ000585
668	JL7141	JMYLRN84WYZ000811	698	DN8885	JMYLRN84WWZ000665
669	JL7491	JMYLRN84WYZ000210	699	CR8990	JMYLRN84WWZ000295
670	GK7182	JMYLRN84WXZ000385	700	HT8991	JMYLRN84WWZ000530
671	KB7263	JMYLRN84WYZ001309	701	JB8311	JMYLRN84WWZ000772
672	FA7882	JMYLRN84WWZ000753	702	DB8880	JMYLRN84WXZ001853
673	CT7888	JMYLRN84WYZ000903	703	HT8898	JMYLRN84WWZ000557
674	FT733	JMYLRN84WWZ000271	704	JC8856	JMYLRN84WXZ001166
675	HT7931	JMYLRN84WWZ000410	705	GU8050	JMYLRN84WXZ000830
676	HZ7182	JMYLRN84WXZ000341	706	FW8106	JMYLRN84WWZ000106
677	HZ731	JMYLRN84WXZ000234	707	CX8306	JMYLRN84WWZ000209
678	GA7898	JMYLRN84WWZ000212	708	HZ8895	JMYLRN84WXZ000798
679	GT7762	JMYLRN84WWZ000746	709	KM845	JMYLRN84W3Z000779
680	KZ7312	JMYLRN84WWZ000695	710	JA8695	JMYLRN84WXZ000353
681	KB7235	JMYLRN84WYZ001494	711	DA8128	JMYLRN84WYZ000707
682	AW7200	JMYLRN84WWZ000766	712	JD8760	JMYLRN84WXZ001125
683	KZ780	JMYLRN84WYZ001412	713	HT8623	JMYLRN84WWZ000549
684	DL717	JMYLRN84WWZ000721	714	HP8982	JMYLRN84WXZ002097
685	JM7031	JMYLRN84WWZ000775	715	JL8013	JMYLRN84WXZ001858
686	FE7417	JMYLRN84WYZ000668	716	JN8299	JMYLRN84WYZ001318
687	JK7126	JMYLRN84WYZ000665	717	JK8678	JMYLRN84WYZ000802
688	GH7978	JMYLRN84WYZ000683	718	HV8341	JMYLRN84WWZ000633
689	CS7882	JMYLRN84WWZ000159	719	MC8209	JMYLRN84W3Z000759
690	JL7580	JMYLRN84WWZ000552	720	KL8474	JMYLRN84WWZ000767

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
721	HV8357	JMYLRN84WWZ000748	751	JN8929	JMYLRN84WWZ000574
722	FX885	JMYLRN84WWZ000655	752	GC8333	JMYLRN84WXZ000169
723	KA8387	JMYLRN84WWZ000251	753	CR8288	JMYLRN84WXZ001974
724	AF8	JMYLRN84WXZ000212	754	JH8349	JMYLRN84WXZ002283
725	JB831	JMYLRN84WXZ001837	755	DB8386	JMYLRN84WWZ000925
726	HZ8968	JMYLRN84WXZ000826	756	EK812	JMYLRN84WXZ001650
727	CA8980	JMYLRN84WWZ000814	757	FH8654	JMYLRN84WWZ000496
728	JA837	JMYLRN84WXZ000397	758	DK8323	JMYLRN84WWZ000751
729	HX876	JMYLRN84WWZ000732	759	DN8898	JMYLRN84WXZ001161
730	HX8722	JMYLRN84WWZ000701	760	JF8900	JMYLRN84WWZ000677
731	HW8680	JMYLRN84WWZ000820	761	HW8321	JMYLRN84WWZ000869
732	FF8286	JMYLRN84WWZ000916	762	EA8087	JMYLRN84WWZ000919
733	JU8112	JMYLRN84WWZ000505	763	ES819	JMYLRN84WWZ000846
734	KB8917	JMYLRN84WWZ000514	764	HX8831	JMYLRN84WWZ000687
735	MJ8879	JMYLRN84WXZ002078	765	JH896	JMYLRN84WXZ002106
736	FP8108	JMYLRN84WWZ000217	766	GU8898	JMYLRN84WWZ000265
737	CK8222	JMYLRN84WXZ002115	767	KN8310	JMYLRN84WWZ000240
738	EY8687	JMYLRN84WYZ001224	768	FE8848	JMYLRN84WWZ000948
739	JC8387	JMYLRN84WXZ001110	769	HM824	JMYLRN84WWZ000461
740	KZ843	JMYLRN84WWZ000125	770	EH8162	JMYLRN84WWZ000860
741	AL8228	JMYLRN84WWZ000336	771	HT8638	JMYLRN84WWZ000578
742	HX8675	JMYLRN84WWZ000696	772	ER8133	JMYLRN84WWZ000464
743	CZ896	JMYLRN84WWZ000135	773	DA8288	JMYLRN84WWZ000770
744	JL8108	JMYLRN84WYZ000719	774	GR8816	JMYLRN84WWZ000404
745	JH8216	JMYLRN84WXZ001154	775	KR8608	JMYLRN84WWZ000103
746	HT8941	JMYLRN84WWZ000297	776	HU810	JMYLRN84WWZ000433
747	JG8148	JMYLRN84WXZ001886	777	JF8113	JMYLRN84WXZ001906
748	LK8247	JMYLRN84WWZ000378	778	FU8738	JMYLRN84WWZ000595
749	AK8078	JMYLRN84WWZ000490	779	GF830	JMYLRN84WWZ000527
750	HW8887	JMYLRN84WWZ000662	780	HH809	JMYLRN84WWZ000642

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
781	HT8085	JMYLRN84WWZ000439	811	GH8878	JMYLRN84WXZ001528
782	GK8883	JMYLRN84WXZ001189	812	EX8329	JMYLRN84WWZ000581
783	CK8021	JMYLRN84WWZ000640	813	KX8206	JMYLRN84WWZ000798
784	GS8115	JMYLRN84WXZ001045	814	KX9957	JMYLRN84WWZ000546
785	DC8345	JMYLRN84WWZ000200	815	EY9914	JMYLRN84WWZ000369
786	HZ8438	JMYLRN84WXZ000812	816	DN9896	JMYLRN84WWZ000386
787	ME8314	JMYLRN84WYZ000705	817	JU9230	JMYLRN84WWZ000224
788	GP8209	JMYLRN84WXZ002014	818	GA9199	JMYLRN84WWZ000168
789	JD8636	JMYLRN84WWZ000255	819	FV9823	JMYLRN84WWZ000130
790	HU8111	JMYLRN84WYZ000681	820	JC984	JMYLRN84WWZ000840
791	DG8001	JMYLRN84WWZ000922	821	HT9271	JMYLRN84WWZ000432
792	HV856	JMYLRN84WWZ000760	822	CC9990	JMYLRN84WXZ001199
793	GV8565	JMYLRN84WYZ000670	823	HU9289	JMYLRN84WWZ000495
794	EJ832	JMYLRN84WXZ002052	824	FC9389	JMYLRN84WXZ000340
795	FA8688	JMYLRN84WXZ001195	825	KG9868	JMYLRN84W1Z000194
796	JM8601	JMYLRN84WWZ000720	826	FF9200	JMYLRN84WXZ001824
797	DT8777	JMYLRN84WWZ000246	827	HJ9827	JMYLRN84WWZ000177
798	JM8415	JMYLRN84WXZ002064	828	KP9407	JMYLRN84WXZ001860
799	FU8011	JMYLRN84WXZ001890	829	BE9388	JMYLRN84WWZ000194
800	HZ8512	JMYLRN84WWZ000762	830	KB936	JMYLRN84WYZ001201
801	LH8870	JMYLRN84WYZ000969	831	JK9105	JMYLRN84WXZ002291
802	LA8020	JMYLRN84WWZ000702	832	HU9066	JMYLRN84WWZ000758
803	HU8214	JMYLRN84WWZ000704	833	HT9757	JMYLRN84WWZ000454
804	GG836	JMYLRN84WWZ000169	834	HX9982	JMYLRN84WWZ000933
805	HZ801	JMYLRN84WWZ000717	835	HS9228	JMYLRN84WYZ000170
806	HT8212	JMYLRN84WWZ000375	836	HW9691	JMYLRN84WWZ000843
807	HJ8818	JMYLRN84WWZ000133	837	GK9299	JMYLRN84WXZ001819
808	JR8565	JMYLRN84WWZ000580	838	LU9555	JMYLRN84WXZ001522
809	GX865	JMYLRN84WYZ001037	839	EB9984	JMYLRN84WWZ000837
810	LY8601	JMYLRN84WYZ000812	840	JC9666	JMYLRN84WXZ001113

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
841	DG9989	JMYLRN84WXZ002314
842	JG9910	JMYLRN84WXZ001663
843	HS9885	JMYLRN84WWZ000290
844	LR9428	JMYLRN84WXZ001788
845	EL956	JMYLRN84W3Z000773
846	BR9996	JMYLRN84WXZ001814
847	GB9668	JMYLRN84WWZ000187
848	HS9992	JMYLRN84WWZ000274
849	GD9011	JMYLRN84WWZ000940
850	FX9380	JMYLRN84WYZ001007
851	EE9984	JMYLRN84WWZ000277
852	JZ9840	JMYLRN84WWZ000649
853	HW966	JMYLRN84WWZ000771
854	HT9618	N84W0010941
855	HY9860	JMYLRN84WWZ000943
856	LP905	JMYLRN84WXZ000432
857	CK920	JMYLRN84WWZ000226
858	HT9067	JMYLRN84WWZ000372
859	KZ9897	JMYLRN84WXZ001141
860	JN9747	JMYLRN84WYZ001306
861	CC9228	JMYLRN84WWZ000559
862	FC9030	JMYLRN84WWZ000162
863	LZ992	JMYLRN84WWZ000170
864	JF9893	JMYLRN84WXZ002318
865	JC9948	JMYLRN84WXZ001630
866	LH915	JMYLRN84WWZ000938
867	ES9116	JMYLRN84WXZ001144
868	GF9882	JMYLRN84WWZ000540
869	HS9699	JMYLRN84WWZ000263
870	HT9097	JMYLRN84WWZ000550

	Reg Mark	Chassis Number
871	HT9194	JMYLRN84WWZ000577
872	HZ9020	JMYLRN84WWZ000784
873	JG9678	JMYLRN84WYZ000398
874	HS9080	JMYLRN84WWZ000296
875	JL9475	JMYLRN84WYZ000876
876	JX9549	JMYLRN84WYZ001263
877	KM9120	N84W0010894
878	FM918	JMYLRN84WWZ000358
879	HS9692	JMYLRN84WWZ000305
880	HS9031	JMYLRN84WWZ000258
881	GF9733	JMYLRN84WYZ000692
882	KB986	JMYLRN84W2Z000421
883	JF9483	JMYLRN84WWZ000202
884	KR9740	JMYLRN84WWZ000674
885	LD9344	JMYLRN84WWZ000310
886	LN961	JMYLRN84WXZ001712
887	JM9141	JMYLRN84WYZ000819
888	KT9346	JMYLRN84WXZ002260
889	JK9805	JMYLRN84WWZ000249
890	JF9671	JMYLRN84WWZ000269
891	FC9189	JMYLRN84WXZ000388
892	JN9507	JMYLRN84WYZ000701
893	CF998	JMYLRN84WYZ001322
894	EA966	JMYLRN84WWZ000537
895	HS9978	JMYLRN84WWZ000625
896	HT9472	JMYLRN84WWZ000554
897	FG7988	JMYLRN84WXZ001175
898	HU1300	JMYLRN84WWZ000484
899	HT8222	JMYLRN84WWZ000395
900	JF1984	JMYLRN84WXZ001843

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Space Wagon N84W

項目 Subject: 改良引擎側罩

Replacement of Engine Room Side Cover

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
901	KX3830	JMYLRN84W3Z000139
902	KU591	JMYLRN84W2Z001109
903	GK819	JMYLRN84WXZ000811
904	CN980	JMYLRN84WWZ000889
905	JN8527	JMYLRN84WWZ000652
906	DR2728	JMYLRN84WXZ001192
907	HS4266	JMYLRN84WWZ000150
908	CW531	JMYLRN84WXZ001902
909	HY355	JMYLRN84WWZ000930