

## Recall Detail

<b>Ref No</b>	<b>10000114</b>
<b>Manufacturer</b>	Land Rover
<b>Vehicle Class</b>	
<b>Model/Type</b>	Discovery Series II/ Defender
<b>Dealer (phone no)</b>	Land Rover Hong Kong (Tel:2110 3022)
<b>Subject</b>	ABS-System Operation
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	N/A
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The brake fluid leak may occur from the ABS modulator cover plate caused the braking efficiency is decreased during brake pedal application
<b>Remedial Action</b>	Replace the ABS modulator cover plate
<b>Build Dates</b>	18.01.1999 to10.12.2003
<b>Launch Date</b>	31/03/2004
<b>Date of Recall Completion</b>	17/07/2012