

Recall Detail

Ref No	10000115
Manufacturer	Land Rover
Vehicle Class	
Model/Type	Discovery Series II
Dealer (phone no)	Land Rover Hong Kong (Tel:2713 1068)
Subject	Active Cornering Enhancement-Torque Concern
Progress	Completed
Affected Vehicle Identification Number (VIN)	N/A
Description of Defect, how it came to light, and possible consequences if ignored.	The banjo connection which secures the Active Cornering Enhancement(ACE) high pressure pipe to the pump may loosen and under certain conditions may allow a fluid leak, which would revert the vehicle handling back to non-ACE operation. In extreme case, should the vehicle continue to be driven, the fluid leak could lead to fire. The loss of fluid would be progressively accompanied by amber and red warning lights on the instrument console.
Remedial Action	Re-torque and replace banjo bolt washers
Build Dates	13.12.1999 to 30.9.2003
Launch Date	31/03/2004
Date of Recall Completion	17/07/2012