

Recall Detail

| | |
|---|--|
| Ref No | 10000116 |
| Manufacturer | Land Rover |
| Vehicle Class | |
| Model/Type | Discovery Series II |
| Dealer (phone no) | Land Rover Hong Kong (Tel:2713 1068) |
| Subject | Incorrect Throttle Operation |
| Progress | Completed |
| Affected Vehicle Identification Number (VIN) | N/A |
| Description of Defect, how it came to light, and possible consequences if ignored. | Misalignment of the spindle bush bore to the break-through bore on the potentiometer side of the throttle body can lead to incorrect throttle operation. Under certain circumstances cause the throttle spindle within the assembly to stick when the throttle pedal is released. Should this occur, the throttle may stick in an open position. |
| Remedial Action | Inspect the date code replace throttle body if necessary. |
| Build Dates | 27/01/2003 to 26/03/2003 |
| Launch Date | 31/03/2004 |
| Date of Recall Completion | 17/07/2012 |