

## Recall Detail

<b>Ref No</b>	<b>10000255</b>
<b>Manufacturer</b>	Lexus
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	LS460 / LS460L
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4922)
<b>Subject</b>	Idler pulleys replacement
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The idler pulleys on the engine may break due to insufficient strength. This may result in clicking noise from engine compartment or warning lamp in the combination meter comes on.
<b>Remedial Action</b>	Replace the idler pulleys
<b>Build Dates</b>	April 2006 ~ June 2007
<b>Launch Date</b>	April 2008
<b>Tentative Date of Recall Completion</b>	July 2017 (completed)