

## Recall Detail

|   |  |
|---|--|
| <b>Ref No</b>   | <b>10000256</b>  |
| <b>Manufacturer</b>   | Lexus  |
| <b>Vehicle Class</b>  | Private Car  |
| <b>Model/Type</b>   | LS460 / LS460L / LS600hL   |
| <b>Dealer (phone no)</b>  | Crown Motors Limited (Tel: 2880 4922)  |
| <b>Subject</b>  | Skid control ECU replacement   |
| <b>Progress</b>   | <b>Completed</b>   |
| <b>Affected Vehicle Identification Number (VIN)</b>                                       | List as below:   |
| <b>Description of Defect, how it came to light, and possible consequences if ignored.</b> | Due to incorrect programming of the Skid Control ECU, the brake warning lamp on the combination meter may turn on and warning buzzer may sound during driving. |
| <b>Remedial Action</b>  | Replace the skid control ECU   |
| <b>Build Dates</b>  | LS460: June 2006 ~ July 2007<br>LS460L: September 2006 ~ July 2007<br>LS600hL: December 2006 ~ July 2007   |
| <b>Launch Date</b>  | April 2008   |
| <b>Tentative Date of Recall Completion</b>  | July 2017 (completed)  |