

Recall Detail

| | |
|---|--|
| Ref No | 10000340 |
| Manufacturer | Lexus |
| Vehicle Class | Private Car |
| Model/Type | IS250 |
| Dealer (phone no) | Crown Motors Limited (Tel: 2880 4922) |
| Subject | Rectify installation of the fuel pressure sensor |
| Progress | Completed |
| Affected Vehicle Identification Number (VIN) | Not applicable |
| Description of Defect, how it came to light, and possible consequences if ignored. | Due to possible improper installation of the fuel pressure sensor connected to the engine fuel delivery pipe, there is a possibility that, in the course of time, the pressure sensor could loosen and result in fuel leakage. |
| Remedial Action | Inspect and retighten the fuel pressure sensor & if needed replace the fuel pressure sensor gasket |
| Build Dates | IS250: August 2007 ~ February 2009 |
| Launch Date | 26 January 2011 |
| Tentative Date of Recall Completion | June 2015 |