

Recall Detail

Ref No	10000350
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	RX400h
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Follow up the Intelligent Power Module in the Inverter
Progress	Completed
Affected Vehicle Identification Number (VIN)	Not applicable
Description of Defect, how it came to light, and possible consequences if ignored.	Certain transistors on the control boards of the Intelligent Power Module in the Hybrid System Inverter may be inadequately soldered and could be damaged from heat caused by high-load driving. If this occurs, various warning lamps will be illuminated on the instrument panel.
Remedial Action	Inspect the inverter assembly & if needed replace it
Build Dates	September 2004 ~ August 2006
Launch Date	30 June 2011
Date of Recall Completion	December 2011