

Recall Detail	
<b>Ref No</b>	10000397
<b>Manufacturer</b>	Mitsubishi Motors Corporation
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	Lancer CY6A
<b>Dealer (phone no)</b>	Sime Darby Motor Services Limited (Tel: 39138800)
<b>Subject</b>	Poor Brake Performance
<b>Progress</b>	Completed
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	In the engine ECU of the affected vehicles, since the control program is inappropriate, if the vehicle is moved under the condition that the steering wheel is operated, air conditioner is ON, vehicle speed is 2.5km/h or less and the accelerator pedal is not depressed (e.g. when drive into garage, etc.) the negative pressure in the brake booster would become insufficient causing the operating efforts of the brake pedal to be increased which could result in the increment of the stopping distance.
<b>Remedial Action</b>	Rewrite the Engine-ECU program.
<b>Build Dates</b>	2012
<b>Launch Date</b>	13/08/2012
<b>Tentative Date of Recall Completion</b>	12/08/2013